

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 34 & 33.

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5626)

-----  
Set post for corner from which:

- A Fir, 30" dia. bears N.12°E., 85 lks. dist.
- A W.Oak, 10" dia. bears S.15°E., 104 lks. dist.
- A Fir, 10" dia. bears S.50°W., 65 lks. dist.
- A Fir, 24" dia. bears N.70°W., 58 lks. dist.

Doug. County Surveyors Office - G.G. Stewart Deputy. Witnesses Frank Evans, H. Stimpson, C. Crocker. Feb. 1922. C.S. File 5/27, M 2-4 & Vol. 3, Pg. 113.

-----  
Set 3/4" Iron Pipe from original BT's standing. Set squared wood marker by pipe.

Doug. County Surveyors Office - James W. Byron, Deputy. April - May, 1957. C.S. File no. 47/180.

-----  
Found - 3/4" I.P. at corner.

Fnd BTs - 10" W.Oak (Byars) down-I open and find scribe marks on chip of old face. Checks for bearing, S.15°E., 63.1' (rec. 68.6').

Also found low cut stumps for S.W. and N.W. BTs - no scribing left. Both BTs check for size, bearing and distances.

New BTs - 6" W.Oak, bears East 4.7' mkd: S27 T28S R4W CS BT.  
10" Maple, bears S.79°W., 29.6' mkd: S33 T28S R4W CS BT.

10" W.Oak, bears S.37°E., 64.5' (on slope) mkd: S34 T28S R4W CS BT.

12" Fir, bears N.36°W., 100.0' (on slope) mkd: S28 T28S R4W CS BT.

B.L.M. Resurvey; Zirpel & Glenn. Under special instructions dated Aug. 29, 1957. (DCSO records Vol. 29, Pg. 12233)

-----  
Found - 1" Iron Pipe.

Fnd BTs - A turnout hole, bears S,15°E., 104 lks. dist. the tree a W.Oak, 12" dia. has slid down hill, no scribe marks visible. (Original)

(Cont. Next Page)

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. to 27, 28, 33 & 34.

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

A sawed Fir stump, 29" dia. bears S.50°W., 65 lks. dist. No scribe marks visible. (Original)  
A sawed Fir stump, 32" dia. bears N.70°W., 58 lks. dist. No scribe marks visible. (Original)  
A W.Oak, 6" dia. bears N.88°E., 7 lks. dist. mkd:  
T28S R4W S27 CS BT. (Byron)  
A W.Oak, 10" dia. bears S.35°E., 86½ lks. dist. mkd:  
T28S R4W S34 CS BT. (Byron)  
A W.Oak, 10" dia. bears S.80½°W., 44 lks. dist. mkd:  
T28S R4W S33 CS BT. (Byron)  
A Fir, 12" dia. bears N.32½°W., 142 lks. dist. mkd:  
T28S R4W S28 CS BT. (Byron)  
Set - an iron post in mound of stone with brass cap mkd:  
T28S R4W  
S 28|S 27  
S 33|S 34  
1958  
Reset iron pipe alongside the iron post.

1958 Brass cap, 3 orig. BTs and 4 Byron BTs, found by BLM in survey by James E. Jelley, under Group #1068, 1981 DCSO records, Vol. 45 Pages 17379-80

Found OK by G. Lang, August 1999 - M133-18 A & B