

PRIMARY CORNER DESCRIPTION 1/4 Cor. between Secs 28 & 27

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5627)

Set Fir post for 1/4 Sec. Cor. from which:
A Fir, 12" dia. bears N.78°E., 18 lks. dist.
A Laurel, 18" dia. bears N.78°W., 43 lks. dist.

Doug. County Surveyors Office - James W. Byron, Deputy.
April-May 1957. C.S. File no. 47/180.

Found - 12" Fir, now 30" N.78°E., 11.9'. I open and find good scribing. The N.W. BT down. I use NE BT to fix position of corner.

Set - An Iron pipe with brass cap at corner point mkd:
T28S R4W
1/4 S 28 | S 27
County Surveyor's Office
1957

New BTs - A Fir, 16" dia. bears S.24°W., 27.9' mkd: 1/4 S28 CSBT
A Cedar, 6" dia. bears S.76°E., 41.1' mkd: 1/4 S27 CSBT

B.L.M Resurvey; Zirpel & Glenn. Under special instructions dated Aug. 29, 1957. (DCSO rec. Vol. 29 Pg. 12234-12235)

Found - County Surveyor's Office BC/IP.
Fnd. BTs- A Fir, 30" dia. bears N.78°E., 18 lks. dist. with fragmentary scribe marks visible on partially opened blaze. (original)
A Cedar, 7" dia. bears S.78°E., 62 1/2 lks. dist. mkd: 1/4 S27 CSBT. (Byron)
A Fir, 16" dia. bears S.20 1/2°W., 42 lks. dist. mkd: 1/4 S28 CSBT. (Byron)

Set - An iron post with brass cap mkd:
T28S R4W
1/4
S 28 | S 27
1958

Reset county surveyor's post alongside iron post.

BLM subd. of Sec. 27, by James E. Jelley, under Group #1068 Survey, June/Aug. 1981 (DCSO records. Vol. 49 Page 17383)

Found 1/4 sec. cor. monumented with an iron post, 2 1/2" dia., firmly set, projecting 8" above ground, with brass cap mkd.
(Cont. Next Page)

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. between Sec's 28|27

Alias	Description

T 28 S R 4 W
1/4
S 28 * S 27
1958

from which the remains of an original bearing tree
A sawed Fir stump 30" dia., bears N.78°E., 18 lks.
dist.; no marks visible.

and the remains of bearing trees mkd. by J.W. Byron in 1957
and described by Zirpel and Glenn in 1958
A Cedar 15" dia., bears S.78°E., 61½ lks. dist.
with healed blaze.

A sawed Fir stump 16" dia., bears S.20½°W., 42 lks.
dist., with fragmentary scribe marks visible
on decayed blaze.

and a new bearing tree
A Fir 7" dia., bears N.54¼°W., 41 lks. dist.,
mkd. 1/4 S28 BT.

Howard Johnstone, For: Roseburg Resources Inc. March, 1990
M 101-75. (Revises M 100-47)

Found - 1958 Cad. brass cap/iron pipe.
Fnd BTs - 12" Cedar, S.78°E., 40.6' healed.
8" Fir, N.54¼°W., 27.1' Partially healed (no
rec.)
16" Fir stump, S.20½°W., 28.4' (rec. 27.7')
30" Fir stump, N.78°E., 11.9'.

Found and used by BLM in a dependent resurvey by Wayne Rogers
Feb. 1996 under group #1794. (DCSO records Vol. 51 Page(s)
19642)

Fd. BC & 3 BTs, by K. Hoffine - Aug. 2012 - M164-14 & REVISED
BY M164-74
