

PRIMARY CORNER DESCRIPTION 1/4 Corner for Secs 34 & 35

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13, Pg. 5620).

Set Fir post for 1/4 sec. cor. from which:
A Fir, 12" dia. bears N.50°E., 32 lks. dist.
A Fir, 12" dia. bears S.89°W., 19 lks. dist.

G.G. Stewart, Deputy Douglas County Surveyor, witnesses:
Frank Evans, H. Stimpson, C. Crocker. Feb. 1922. C.S. File 5/27, M 2-4 & Vol. 3, Pg. 113.

Set - Iron Pipe for Corner. Found 2 original bearing trees, both badly rotted. Marked the following trees:
Fir, 24" dia. bears N.26½°E., 49.0'.
Fir, 18" dia. bears S.64°W., 33.6'.

James W. Byron, Milo Godfrey, S.A. Bilow - County Surveyor's Office. - May 15, 1958, C.S. File No. 49/67-3

Found - ½" Iron Pipe at corner & both BTs as recorded by Stewart in 1922.
Fd BTs - 24" now 30" Fir N.26½°E., 49.0', has good bark scribing "¼ CS BT"
S.W. BT now stump only, bark gone, no scribing found.
Set brass cap alongside ½" Iron Pipe mkd:
¼ S34|35 T28S R4W County
Surveyor's Office, 1958
New BTs- 22" R.Fir, bears S.49°E., 46.4' mkd: ¼ S35 CSBT.
13" Cedar, bears N.35°E., 48.7' mkd: ¼ S35 CSBT.
Note - No trees near to the west.

B.L.M. Resurvey by Zirpel & Glenn, under special instructions dated Aug. 29, 1957. (DCSO records Vol. 29, Pg. 12229-12230)

Found - Doug. County Surveyor's Office Brass Cap (1958)
Fnd. BTs- (Original) A rotted sawed fir stump, 24" dia. bears S.89°W., 19 lks. dist. No scribe marks visible.
(Stewart 1922) A Fir, 37" dia. bears N.26½°E., 74 lks. dist. with scribe marks ¼ CS BT visible on bark blaze.
(Stewart 1922) A sawed Fir stump, 25" dia. bears S.64°W., 51½ lks. dist. No scribe marks visible.
(Byron 1958) A Cedar, 13" dia. bears N.34°E., 74 lks. dist. mkd: ¼ S35 CS BT on open blaze.
(Byron 1958) A Fir, 22" dia. bears S.49°E., 69 lks. dist. mkd: ¼ S35 CS BT on open blaze.

Continued next page

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 500140

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 34 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Set an iron post with Brass Cap marked:
T28S R4W

¼

S34|S35

1958

New BT - A Fir 15" dia. bears N.11½°W., 222 lks dist., mkd:
¼ S34 BT.

Note - Reset County Surveyor's cor. material alongside iron
post.

Found OK, 9/85 - B. Holt M 99-40

Found OK by G. Lang, August 1999 - M133-18 A & B