

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec Cor 12 & 13; 7 & 18, T28-3

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

Original - W.H. Byars, under contract # 376 dated Jan. 22, 1881 (DCSO rec. Vol. 13 Page 5527)

Set post for sec. cor. to secs. 7, 12, 13 and 18, from which
A Laurel 24" dia. bears N.55°E., 65 lks. dist.
A Laurel 18" dia., bears S.85°E., 54 lks. dist.
A Fir 28" dia., bears S.44°W., 37 lks. dist.
A Cedar 60" dia., bears N.70°W., 45 lks. dist.

J.H. Markham, May 10, 1952 - C.S. File 41/34

(Determined by old BTs.) Typed from old
(Set 1" x 30" Iron Pipe.) typed renewals
(19" Laurel which bears S.5°W., 23.6 ft.)
TYPED FROM ACTUAL NOTES: (added 6/18/2024 JC DCSO)
Determined by OBTs
Found - A Cedar 60" dia., bears N.70°W., OBT.
A Laurel 30" dia., bears S.85°E., 31.5' OBT. I
remarked S18 T28S R3W BT.
At corner point set 1"x30" IP, from which
A Laurel 19" dia., bears S.50°W., 23.6' mkd S13 T28S
R4W 2880 BT

Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam - July 1961 - C.S. file 49/67-17

Found - 1" I.P. at corner.
Orig. 24" now 30" Laurel N.55°E., 42.9 ft., shows old scribing.
Orig. 60" now 60" Cedar, face & side gone, burned out.
Fir snag, rotted that checks for SW BT.
Set Brass cap alongside 1" I.P. marked:
County Surveyor's S12 | S 7 T28S
Office, 1961 R4W S13 | S18 R3W
New BTs -60" Cedar, O.B.T., bears N.70°W., 29.7 ft. scribed by others, S12.
20" Laurel bears S.55°W., 23.5 ft. scribed by others, S13 T28S R4W 2880.
R.Fir bears S.37°E., 25.0 ft. scribed S18 T28S R3W CS BT.

(Cont. Next Page)

TOWNSHIP 28 RANGE 04 POINT IDENTIFIER # 700500

PRIMARY CORNER DESCRIPTION Sec Cor 12 & 13; 7 & 18, T 28-3

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

BLM resurvey, by John M. Jelley, under Group #570, Survey June/July 1965 (DCSO records, Vol. 33 Pages 13932-33)

Found 1961 County brass cap, from which the original bearing trees:

- A Madrone 38" dia., bears N.59°E., 58 lks. dist., with scribe marks 8 BT visible on partly healed blaze. (Record, N.55°E., 65 lks.)
 - A Madrone 30" dia., bears S.85°E., 44 lks. dist., with scribe marks T28S R3 BT visible on partly healed blaze. (Record 54 lks.)
 - A rotted Fir snag 35" dia., bears S.40°W., 42 lks. dist. with no marks visible. (Record S.44°W., 37 lks.)
 - A fire damaged Cedar 60" dia., bears N.70°W., 45 lks. dist. with scribe marks S12 visible on new blaze, no original marks visible.
- and bearing tree marked by Byron
- A Fir 15" dia., bears S.37°E., 37 lks. dist., with illegible scribe marks visible on partly healed double blaze.
- and a bearing tree of which I have no record
- A Madrone 20" dia., bears S.55°W., 35 lks. dist., with scribe marks S3 28S R4W 2880 visible on partly healed blaze.

Add marks BLM 1965 to brass cap.

Fd. OK by Edwards, June 1998 - M 128-70.