

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. 32 & 33; 4 & 5, T29-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5652)

Set post corner to secs. 32, 33, 4 & 5, from which
A W.Oak 40" dia., bears S.63 3/4°W., 377 lks. dist.
A Y.Oak 20" dia., bears S.31°E., 636 lks. dist.
A Y.Oak 24" dia., bears N.3 1/2°W., 228 lks. dist.
A Y.Oak 30" dia., bears N.20 1/2°E., 233 lks. dist.

H.L. Eppstein, Wit: Bill Dolan; S.D. Whitsett - May 10, 1926
- C.S. File 3/54; "old" cor. book, page 105

I renewed this corner from 3 old BTs. Other tree was gone.
Set Oak Post. Fence post at corner. Old BTs are badly rotted.
Marked new BTs as follows:
B.Oak 20" dia., bears S.66°W., 170.7 ft.
B.Oak 14" dia., bears N.28°30'W., 68.8 ft.
W.Oak 10" dia., bears N.78°E., 148.8 ft.
B.Oak 10" dia., bears S.24°E., 120.0 ft.

Doug. County Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - Sept/Oct. 1961 - C.S. File 49/64-16

Found - All 4 BTs as recorded by Eppstein. See book 1 Pg. 104, distance to NE BT should be 120.0 ft. and dist. to SE BT should be 148.8 ft. All BTs show good scars. Do not open.
Set brass cap at cor. mkd: County Surveyors S32|S33 T28S
Office 1961 S 5|S 4 T29S^{R5W}
No new bearing trees scribed.
Corner is under East-West fence.

William Ruppert - For: Ron Kuehn - Oct. 1980 - M 84-58

Found - 2 1/2" brass cap
28" W.Oak S.76 3/4°W., 118.7 ft. Scar.
28" B.Oak S.22 3/4°E., 146.9 ft. Scar.
36" B.Oak S.65 3/4°W., 174.1 ft. Scar.
B.Oak N.30 1/4°W, 69.0 ft. Scar.
Note rotation error of 3° on Maps M82-10 and M81-29 and corresponding rotation of BTs.