

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. 28, 29, 32 and 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5665)

Set post corner to secs. 28, 29, 32 and 33, from which
A W.Oak 15" dia., bears S.28½°W., 740 lks. dist.
A W.Oak 26" dia., bears N.13°W., 414 lks. dist.
A Y.Oak 12" dia., bears N.36 3/4°E., 114 lks. dist.
A Y.Oak 10" dia., bears S.87 3/4°E., 816 lks. dist.

J.W. Cole, Witnesses: Smith, Stone & Jennings - Vol. 3 Page 86; Field Book 50 Page 34

I renewed this corner from two original trees. From the large Oak which I chopped open and found the scribe marks, I ran S.13°E., 273.4 ft. and set a stake from which a large B.Oak bears S.29°W., 490 ft. I set an Oak post 4 x 4 x 40 for corner and also an iron pipe 2" x 30".

New trees marked:

B.Oak 15" dia., bears N.40°E., 74 ft.
W.Oak 12" dia., bears N.28°W., 185 ft.

Doug. County Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - Sept/Oct. 1961 - C.S. File 49/64-19

Found - 2" I.P. at corner & both BTs as recorded by Cole.
We open NW BT & find good scribing.
NE BT shows good scar but may die, result of 1961 fire.

Rescribe NW BT "S29 CS BT T28S R5W.

New BT -11" W.Oak bears N.67°E., 139.3 ft. scribed T28S R5W S28 CS BT.

No other BTs near.

Corner is under E-W fence.

Found OK, Nov. 1987, D. Bentz, M 105-13 ABC

Doug. County Surveyors Office - Randall Smith; Stephen Flause - Aug. 8, 1989 - C.S. File 64/1-13

Found - A 1¼" iron pipe (rec. 2") protruding 5" above ground.

12" now rotted Oak of indeterminable size, no scribing, blazes or axe marks see, bears N.36 3/4°E., 75.2 ft. (agrees w/record) Possible orig. BT.

(Cont. Next Page)

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. cor. 28, 29, 32 & 33

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

15" now 30" dia., 2½ ft. high Oak stump with possible blaze seen from top, bears N.40°E., 74.7 ft. (Rec. N.40°E., 74 ft., possible face measurement.)

12" now 15" dia. W.Oak with a fully healed double blaze bears N.28°W., 185.0 ft. (agrees w/rec)

11" now 18" dia. W.Oak with a fully healed single blaze bears N.67°E., 139.3 ft. (agrees w/rec)
(This tree to be cut in near future)

Set a 2 3/8" dia. DCSO brass cap on a 1 3/8" O.D. x 32" long I.P. is set in ground at referenced position of 1¼" I.D. Iron pipe. DCSO BC/IP protrudes 6" above ground, 1¼" I.P. is set along north edge of BC/IP and protrudes 5" above ground. Cap stamped: "Douglas County Surveyors T28S S29 S28 S32 S33 R5W 1989 Office"

1¼" iron pipe measured 23½" long.

New BTs -13" dia. W.Oak double blazed & scribed "T28S R5W S28 CS BT"

12" dia. Ash (northerly tree in a cluster of Ash) double blazed and scribed "T28S R5W S33 CS BT" bears S.23°E., 333.7 ft.

Corner lies 4 ft. North of East-West fence line on the West edge of a small southerly running draw. No trees at a reasonable distance southeast of corner.