

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Pages 5656-57)

Set post corner to secs. 27, 28, 33 and 34, from which
A Y.Oak 14" dia., bears S.30°W., 38 lks. dist.
A W.Oak 14" dia., bears N.33½°W., 82 lks. dist.
A W.Oak 13" dia., bears N.13°E., 44 lks. dist.
A W.Oak 15" dia., bears S.51°E., 156 lks. dist.

Briggs, April 1893 For: Charles Fogg; Charles Blackman; Thomas Blackman - Vol. 1 Pag 240-241

One of the original BT standing. The others destroyed by cutting down, stumps remaining. Set post 4 ft. long 4" sq. 24" in the ground marked as per instructions. Made 3 new BTs to wit:

W.Oak 20" dia., bears N.24°E., 61 lks.
W.Oak 6" bears N.61°W., 60 lks.
W.Oak 30" bears S.51½°E., 155 lks.
Orig. BT, B.Oak 16" dia. bears S.30°W., 38 lks.

John H. Markham, Jr. - Geo. Vaughn, witness - For: Stomar Lbr.- Aug. 1950 - C.S. File 40/272-5

Determined by old BT.
A B.Oak 28" dia., bears N.24°E., 40.2 ft., I rescribe S27.
A B.Oak stump bears S.30°W., 25.0 ft.
At corner point, set 3/4" x 30" Iron pipe 18" in ground, from which

A W.Oak 6" dia., bears N.58°W., 39.8 ft. dist. mkd.
S28 2880 BT.
A W.Oak 7" dia., bears S.10°W., 34.0 ft. mkd. S33
2880 BT.
A W.Oak 6" dia., bears S.23°E., 21.0 ft. mkd. S34
2880 BT.

BLM resurvey by Bedell and Peterson, under Group #1425. Survey April, 1988-April 1990 (DCSO records, Vol. 49 Page 18708-9)

The cor. of secs. 27, 28, 33, and 34, perpetuated and recorded by Briggs, in 1893, and further perpetuated and recorded by Markham, in 1950, monumented with an iron pipe, 1¼" dia., firmly set, projecting 8" above the ground, from which the remains of an original hearing tree:

continued next page

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 27, 28, 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A root hole, bears S.30°W., 38 lks., with a down and rotted oak alongside, size indeterminate, with axe marks visible on rotted blaze.
and bearing trees mkd. by Briggs
An oak, 34" dia., bears S.51°E., 153 lks., with healed blaze.
An oak, 12" dia., bears N.59°W., 60½ lks., with a partially healed over rotted blaze.
and bearing trees mkd. by Markham
An oak, 16" dia., bears S.24½°E., 33 lks., with healed blaze.
An oak, 13" dia., bears S.10°W., 52 lks. with healed blaze.
At the corner point
Set a stainless steel post, 28" long, 24" dia., 22" in the ground, directly over the iron pipe, with brass cap mkd.
T28S R5W
S 28 | S 27
S 33 | S 34
1988
from which a new bearing tree
An oak, 12" dia., bears N.71½°E., 32 lks., mkd. T28S R5W S27 BT on the bark.

Douglas Co. Surveyors Office - Stephen J. Flause - Kody Inda
- 8/2008 - C.S. File 67/25-66

Found all BLM described BTs alive except OBT (34" Oak, S.51°E., 153 lks.) which is now sound standing dead tree.