

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 440300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 and 27

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5682)

Set 1/4 sec. post, from which
A W.Oak 16" dia., bears S.61 3/4°E., 138 lks. dist.
A Maple 14" dia., bears N.85°W., 119 lks. dist.

BLM resurvey by Peterson & Bedell under Group #1425 - Survey, April 1988-April 1990 (DCSO records, Vol. 49 Page 18712)

The 1/4 cor., determined at record bearing and distance, from the remains of an original bearing tree:
A sawed Oak stump 18" dia., bears S.61 3.4°E., 138 lks. dist. with axe marks visible on a rotted blaze.

At the corner point
Set a stainless steel post, 28 ins. long, 2 1/2 ins. diam., 25 ins. in the ground, with brass cap mkd: T 28 S R 5 W

1/4 S 22
 S 27
 1988

from which new bearing trees
A Fir 14" dia., bears S.5°E., 20 lks. mkd. 1/4 S27 BT.
A Fir 5" dia., bears N.44 1/2°W., 60 lks. mkd. 1/4 S22 BT.
Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.
The cor. is located on a NW slope, 25 lks. S. of a creek, 4 lks. wide, course N.80°W., and 60 lks. N. of a wire fence line, extending E. and W.

Fd. Ok by D.Edwards, 10/96, M 126-10.