

TOWNSHIP 28 RANGE 05 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 13 Page 5681)

Set post corner to secs. 14, 15, 22 and 23, from which
A Y.Oak 12" dia., bears S.13°E., 20 lks. dist.
A Y.Oak 14" dia., bears S.73°W. 15 lks. dist.
A Y.Oak 8" dia., bears N.33°W., 45 lks. dist.
A Y.Oak 15" dia., bears N.17°E., 34 lks. dist.

Ben B. Irving, D.C.S. - Wit: N.E. Richardson; Blinn Cooper; Wesley French; Frank Bohme - Jan. 6, 1938 - (No record source found, see "old" corner book, page 105)

Location determined from 12" B.Oak. Orig. BT N.35°W., 45 lks. which we chopped out. Scribe marks plain and legible. Tree fell due to its weight being all on one side.
A B.Oak rotten stump N.17°E., 34 lks. with hole where BT destroyed but evidences of stump and roots checked location for bearing and distance.
Set a sandstone 8" x 10" x 16", 12" in ground for corner, from which
Fir 12" dia., bears N.12°E., 44 lks. dist.
Fir 12" dia., bears S.86°W., 23 lks. dist.
Fir 10" dia., bears S.41°E., 24 lks. dist.
Fir 14" dia., bears N.36°W., 60 lks. dist.

Doug. County Surveyors Office - James W. Byron, deputy - M. Godfrey; S. Bilow - For: Office records. Nov. 1957 - C.S. File 49/21-40

Found - Stone & all BTs set by B.B.I. in 1938. BTs are stumps only now. I open SE and SW BTs and found good scribing.
Set Brass cap alongside of cor. stone mkd: S15|S14 T28SR5W
County Surveyor's Office, 1957 S22|S23
New BTs -10" R.Fir N.2½°W., 65.4 ft. scribed S15 T28SR5W CSBT
14" R.Fir S.45°W., 18.5 ft. scribed S22 T28SR5W CSBT
10" R.Fir N.40°E., 31.5 ft. scribed S14 T28SR5W CSBT
16" R.Fir S.84°E., 27.6 ft. scribed S23 T28SR5W CSBT

Found OK, August, 1990 - M 110-57