

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 4 & 9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5731)

-----  
Set 1/4 sec. post, from which  
    A Y.Oak 20" dia., bears S.54°E., 195 lks. dist.  
    A W.Oak 24" dia., bears N.57½°E., 265 lks. dist.

Doug. County Surveyors Office - June 27, 1957 - C.S. File 47/196

-----  
Corner located from 20" B.Oak S.54°E., 128.7 ft. (now 40" dia.) which was chopped open several years ago - face and scribe marks (1/4 SBT) plainly visible. Tree alive & standing & apparently in good condition. Corner falls in fence corner - fences E. W. and South. At bearing & distance for other BT, (N.57½°E., 175.0 ft.) found uprooted oak stump, face down. As it was too heavy to move, could not check for scribing, but assume it to have been the other BT.

Set I.P. with brass cap at corner point stamped "County Surveyors Office 1957, T28S R6W 1/4 S4|9"

Marked new trees:

    17" D.Fir N.38°E., 37.0 ft. scribed 1/4 S4 CS BT.  
    18" D.Fir S.7°E., 27.6 ft. scribed 1/4 S9 CS BT.

Doug. County Surveyors Office - Karen Reed; Frank Silagy - Feb. 12, 1979 - C.S. File 60/24-8

-----  
Found - DCSO brass cap 18" above ground, located at fence cor. with E-W fence and S. fence.

    20" now 40" B.Oak bears S.54°E., 128.7 ft. with chopped out blaze visible scribing "1/4 BT" (Orig.)

    A 2 ft. high 21" Fir stump bears S.7°E., 27.6 ft. No visible evidence of blaze or scribing. Could possibly be SE BT from 1957.

    17" now 22" D.Fir bears N.38°E., 37.0 ft. with well healed blaze.

    No other original trees found.

New BTs - 35" Pine bears N.62°W., 44.9 ft. scribed "1/4 S4 CSBT" in double blaze.

    14" D.Fir bears S.34°W., 25.9 ft. scribed "1/4 S9 CSBT" in double blaze.

Fd. Ok by Raymond Brown, May 2004-Sept. 2008 - RM 4-16