

TOWNSHIP 28 RANGE 06 POINT IDENTIFIER # 400200

PRIMARY CORNER DESCRIPTION Sec Cor 27, 28, 33 & 34

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Elder and Gile, under Contract #31 dated April 7, 1853 (DCSO records, Vol. 14 Page 5716)

Set post cor. to secs. 27, 28, 33 and 34, from which
A Y.Oak 12" dia., bears S.40°E., 65 lks. dist.
A Y.Oak 24" dia., bears S.18°W., 55 lks. dist.
A Y.Oak 16" dia., bears N.50°W., 168 lks. dist.
A Y.Oak 15" dia., bears N.60°E., 103 lks. dist.

Doug. County Surveyors Office - James Byron, Deputy - Dale McFarland; John Powell - Dec. 1961 - C.S. File 49/139-11

Found - Orig. 16" now 30" B.Oak N.50°W., 110.9 ft., open & find good scribe "S".
Also find remnants & stump hles for SW., NE., and SE BTs.

Set brass cap at cor. mkd: County Surveyor's S28|S27 T28S R6W
Office, 1961 S33|S34

New BTs - 10" W.Oak bears N.15°E., 19.8 ft. scribed S27 T28S R6W CS BT.
22" R.Fir bears S.24°E., 32.9 ft. scribed S34 T28S R6W CS BT.
7" Laurel bears S.46½°W., 19.0 ft. scribed S33 CSBT.
16" R.Fir bears N.73°W., 30.2 ft. scribed S25 T28S R6W CS BT.

Howard Johnstone - For: Roseburg Forest Products - Crew: F. White; F. Raddatz; B Olson - Oct. 15, 1986 - C.S. File 63/26-3

Found - Cap bent over and all BTs down and rotted.
10" W.Oak N.15°E., 19.8 ft. down & rotted.
22" R.Fir S.24°E., 32.9 ft. down and rotted.
7" Laurel S.46½°W., 19.0 ft. down and rotted.
16" R.Fir N.73°W., 30.2 ft. down and rotted.
30" B.Oak N.50°W., 110.9 ft. down and rotted. (orig.)
Reset I.P./B.C. from BT root holes and rotted stumps. Painted exposed pipe and BTs with yellow paint.
New BTs - 5" Madrone N.77°W., 7.5 ft.
8" Madrone S.53°W., 32.5 ft.
6" Madrone S.4°E., 31.5 ft.
Marked these trees with a face, scribed and tagged.

Found OK by D. Beedle, June 2000 - M135-24