

TOWNSHIP 28 RANGE 07½ POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec Cor 19 & 30; 24 & 25, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn, Deputy, Contract #57 dated April 12, 1855 (DCSO records, Vol. 14 Page 5790-91)

Set post, cor. of secs. 19, 30, 24 and 25, from which

- A B.Oak 24" dia., bears N.58°E., 30 lks.
- A B.Oak 15" dia., bears N.18°W., 38 lks.
- A B.Oak 24" dia., bears S.72°W., 30 lks.
- A B.Oak 15" dia., bears S.72°E., 76 lks.

Jesse W. Cole, County Surveyor - Wit: W.H. Coats, Walter Coats; N.E. Richardson - Feb/March 1923 - C.S. File 5/37; Vol. 3 Pgs. 141-147; M 1-2

Renew this cor. from orig. bearing trees:

- Large Bl. Oak bearing scribe marks, N.58°E., 30 lks.
 - 20" W.Oak bearing scars, S.72°E., 76 lks.
 - A hole where a tree stood, bears N.18°W., 38 lks.
 - A stump of a large B.Oak, S.72°W., 30 lks.
- Set fir post 5" x 5" x 50", also two conglomerate rocks, 8" x 10" x 12", from which
- 8" Fir bears N.46°15'E., 17.6 ft.
 - 10" Fir bears S.38°W., 19.8 ft.
 - 12" Fir bears N.24°W., 12.3 ft.
 - 24" Fir bears S.52°30'E., 20.0 ft.

GL0 resurvey by Mensch, 1924 (DCSO records, Vol. 14 Page 5918)

Intersect the point for cor., located by record measurement from the orig. bearing trees.

At the exact cor. point

Set an iron post, 3 ft. long, 2 ins. diam., 27 ins. in the ground, with brass cap mkd:

T28S
R8W:R7½W
S24:S19
S25:S30
1924

from which (new bearing trees)

- A Fir 10" dia., bears N.46°E., 26 lks. dist. mkd. T28S R7½W S19 BT.
- A Fir 20" dia., bears S.54°E., 30 lks. dist., mkd. T28S R7½W S30 BT.
- A Fir 12" dia., bears S.37°W., 29 lks. dist., mkd. T28S R8W S25 BT.
- A Fir 14" dia., bears N.14°W., 19 lks. dist., mkd. T28S R8W S24 BT.

from which (Original bearing trees)

(Cont. Next Page)

TOWNSHIP 28 RANGE 07½ POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. 19 & 30; 24 & 25, T28-8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A B.Oak 36" dia., N.58°E. 30 lks., marks legible.
A B.Oak 24" dia., S.72°E., 75 lks., blazes plain
A B.Oak, snag, S.65°W., (Not S.72°W) 30 lks. marks rotted away.
A B.Oak rotted down, stump hole shows position, bears N.11°W., (Not N.18°W.) 38 lks.

Doug. County Surveyors Office - James Byron, Deputy
Milo Godfrey; Clete Putnam - May 1961 - C.S. File 52/79-4

Found - Brass cap at corner and stump of SE BT, shows good scribing. No trace of other BTs found.
New BTs -6" R.Fir bears S.22°W., 54.6 ft. scribed S25 CSBT.
20" R.Fir, N.9°E. 46.0 ft scribed S19 T28S R7½W CSBT
Cor. lies 38 ft. westerly from fence intersection.

FD BC and BTs 12/2024 by N Hibbs M185-21