

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for secs. 22 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Nathaniel Ford, under Contract #44 dated May 30, 1854 (DCSO records, Vol. 14 Pages 5758-59)

Set quar. sec. post, from which
A B.Oak 20" dia., bears S.77°E., 80 lks. dist.
A B.Oak 24" dia., bears S.85°W., 185 lks. dist.

Doug. County Surveyors Office - B.B. Irving - R.L. Irving;
R.E. Jennie - C.S. File 37/151 - March 1926

Found - Orig. BTs which were badly rotted.
Set an Oak post for corner, from which
B.Oak 6" dia., bears S.62°39'W., 19.4 ft.
B.Oak 8" dia., bears S.55°55'E., 40.6 ft.

Doug. County Surveyors Office - James Byron, Deputy - Clete Putnam; Milo Godfrey - March 1961 - C.S. File 49/50-43

Found - B.Oak, now 8½", showing good scars, S.62½°W., 19.4 ft. Did not open.
8" B.Oak snag, S.56°E., 26.6 ft., instead of 40.6 ft.) with nearly rotted old face showing good scribing "S23 CS".
Orig. B.Oak, now 40", S.77°E., 52.8 ft., showing scar. This tree nearly dead. Has never been opened to face.
Set Iron pipe with brass cap at cor. mkd: "County Surveyors Office, 1961 T28S R7W ¼ S22|S23".
New BT - 18" Madrone S.84°E., 23.2 ft. mkd. "¼ S23 CS BT".

Found OK, Donald Bentz, December 1987, M 105-35

Bruce Shaner - June 30. 1997 - C.S. 65/15-3E & M 124-56

Found - 2½" Brass cap on a 1" iron pipe
12" B.Oak BT Snag face overgrown, bears S.62½°W. 19.4'
8" B.Oak BT, bearing S.56°E., 26.6', now gone
40" B.Oak BT, now dead, bears S.77°E., 52.8'
26" Madrone BT, face 0/grown, bears S.84°E., 23.2'.
New - 10" D.Fir BT, I scribed "¼ S22 BT", bears N.66°W., 23.3'.
8" D.Fir BT I scribed "¼ S22 BT" bears S.18°W. 12.5'
6' steel fence post, I set north 1'

Fd. Ok by G. Lang, 8/2009 - M159-73