

PRIMARY CORNER DESCRIPTION Angle Point 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey, Dennis Hathorn, under Contract #57 dated April 12, 1885 (DCSO records Vol. 12 Page(s) 5230)

Set ¼ sec. post, from which:
 An Oak, 24" dia., bears S.21°E., 372 lks.
 An Oak, 20" dia., bears S.26°W., 250 lks.

GLO survey by F. Mensch, Contract #109 dated 1924 (DCSO records Vol. 14 Page(s) 5844)

Intersect the cor. established by Hathorn, for the standard ¼ sec. Cor. Of sec. 4, located by measurement from the stumps of the original bearing trees, marks eroded by weather and decay, but identified unmistakably by position, and no other stumps or trees near.
At the exact cor. point
Set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for angle point, with brass cap marked:
 AP 11 S33
 1924
from which (new bearing trees):
 An Ash, 10" dia., bears N.65½°E. 350 lks., mkd: AP BT
 A W.Oak, 5" dia., bears N.57½°W. 113 lks., mkd: AP BT