

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 903160

PRIMARY CORNER DESCRIPTION Angle Point S. bdy Sec. 32, T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Dennis Hathorn under Contract #57 dated April 12, 1855 (DCSO records, Vol. 14 Page 5231)

Set post, cor. of secs. 5 and 6, from which
A Fir 30" dia., bears S.71°W., 22 lks.
A Maple 12" dia., bears S.44°E., 42 lks.

GL0 resurvey by Mensch, 1924 (DCSO records, Vol. 14 Page 5850)

Intersect the cor. established by Hathorn for standard cor. of secs. 5 and 6, located by measurement from the original bearing trees. The SW tree has been cut down, marks legible on the stump. The SE tree shows old blazes, marks overgrown. At the exact cor. point
Set an iron post, 3 ft. long 1" dia., 28" in the ground, for angle point, with brass cap marked: AP
1924

from which
(Old bearing tree), A Maple 14" dia., bears S.44°E., 42 lks. dist., re-marked A P BT.
(New bearing tree) A Fir 36" dia., bears S.46°W., 72 lks. dist., marked A P BT.

Doug. County Surveyors Office - James Byron, Deputy - Milo Godfrey; Clete Putnam - Feb/March 1961 - C.S. File 49/79-32

Angle point, S.38°21'W., 7.38 chs. from NE Cor. Sec. 6
Found - Brass cap. SW BT, now stump. SE BT, shows scar.
New BTs - 20" Myrtle bears N.63½°E., 40.0 ft. scribed AP CSBT
6" W.Fir bears N.55½°W., 42.6 ft. scribed AP CS BT.

Fd. Ok by D.Edwards, 11/96, M 126-13.

Fd. OK by McLind, surveyed Dec. '96 thru Feb. '98 - M 128-40

Douglas Co. Surveyors Office - Randall W. Smith - Stephen J. Flause - 5/28/1998 - C.S. File 66/2-41

Found - 2½" dia., brass cap on a 1" O.D. iron pipe, protrudes 6" above ground, properly marked.
1924
12" now rotted Maple found at record bearing S.44°E., 27.7 ft." Note newer Maples are growing from this OBT.
(Cont. next page)

TOWNSHIP 28 RANGE 07 POINT IDENTIFIER # 903160

PRIMARY CORNER DESCRIPTION Angle Point South Bdy Sec 32, T27-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

6" now badly rotted W.Fir stump with axe mark, no scribing visible, near record "N.55½°W., 42.6 ft." 1961

20" now 22" dia., Myrtle with a fully healed double blaze, bears N.63½°E., 40.0'. Agrees with rec. 1961

36" now 32" dia., 5 ft. high D.Fir stump with a fully healed single blaze, bears S.46°W., 47.5'. (Agrees with rec. dist. is to blaze) 1924

New BTs- 12" dia., Maple double blazed and scribed "AP S32 CS BT" bears S.44°E., 26.1'.

6" dia., Maple double blazed and scribed "AP S32 CS BT" bears N.32½°W., 7.2'.

Corner lies approx. 50' south of a creek on a steep North slope.