

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T28-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5787)

-----  
Set post cor. secs.18, 19, 13 and 24, from which  
A Maple 6" dia., bears S.30°W., 3 lks. dist.  
A Maple 6" dia., bears N.30°W., 4 lks. dist.  
A Laurel 6" dia., bears N.25°E., 30 lks. dist.  
A Fir 30" dia., bears S.60°E., 36 lks. dist.

Survey by John Safstrom - For: Coos Bay Timber - Sept. 1961  
-C.S. File 63/161-10

-----  
Found - The Orig. BT for sec. 19, which is a36" D.Fir.  
Set - 1½" iron pipe 3 ft. long was driven 2 ft. in ground  
for sec. cor. post by this survey.  
Hemlock, 16" dia. S.19°45'W. 15.8 ft. scribed S24 BT  
Hemlock, 8' dia. N.68°15'W. 15.1 ft. scribed S13 BT.  
Yew, 5" dia., N.75°45'E., 12.8 ft. scribed S18 BT.  
Distances are to center of trees.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken  
and Albert Garrison, Cadastral Surveyors, under Group #'s 691  
and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol.  
36 Page(s) 15089-90)

-----  
The Sec. Cor., perpetuated & recorded by John L. Safstrom in  
1961, monumented with an iron pipe 1½" dia., firmly set,  
protruding 4" above ground, from which the remaining orig BT:  
A Fir 45" dia., bears S.60°E., 36 lks. dist. with scribe  
marks 8 BT visible on weathered bark blaze.  
and bearing trees mkd. by Safstrom  
A Yew 5" dia., bears N.71½°E., 19 lks. dist., with scribe  
marks S8 BT visible on open blaze.  
A Hemlock 18" dia., bears S.21°W., 24 lks. dist., with  
scribe marks S24 BT visible on open blaze.  
A Hemlock 10" dia., bears N.69°W., 23 lks. dist., no marks  
visible on healed blaze.

At the corner point  
Set an iron post, 28" long, 2½" dia., 24" in the ground, with  
brass cap mkd:

T 28 S  
R 9 W R 8 W  
S 13 | S 18  
S 24 | S 19  
1972

Reset iron pipe alongside iron post.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T28-9

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2012, surveyed April 2002/March 2003 - (DCSO rec. Vol. 54 Page(s) 21190-1)

-----  
The cor. of secs. 13, 18, 19, & 24, on the E. bdy. of the Tp., monumented with an iron post, 2½" dia., firmly set, projecting 2" above the ground, (alongside an iron pipe, 1½" dia.) with brass cap (properly) mkd., from which the remains of an original bearing tree

A fir stump, 45" dia., bears S.54°E., 23.8 ft., with a healed blaze (Record, S.60°E.).

and the remains of bearing trees mkd. by Safstrom in 1961, reported by Roseberry et. al. in 1972

A yew snag, 5" dia., bears N.71½°E., 12.5 ft., with scribe marks S8 BT visible on partially open blaze.

A hemlock, 25" dia., bears S.21°W., 15.8 ft., with a healed blaze.

A hemlock, 17" dia., bears N.69°W., 15.2 ft., with a healed blaze.

and bearing trees mkd. by person(s) unknown

A hemlock, 11" dia., bears S.29½°E., 17.2 ft., with scribe marks T28S R8W S19 BT visible on partially opened blaze.

A fir stump, 61" dia., bears S.5¾°W., 20 ft., with a healed blaze.

A hemlock, 26" dia., bears N.2½°W., 2.4 ft., with a healed blaze.

and a new bearing tree

A hemlock, 13" dia., bears N.50¼°E., 26.9 ft., mkd. T28S R8W S18 BT.

Each new bearing tree has a 2½"x ¼" magnetic nail (Mag Nail) driven at the base right side-center, unless otherwise described in the corner description

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2100, surveyed Sept. 2004 - (DCSO rec. Vol. 55 Page 21500) & 2008 BLM plat

-----  
The corner descriptions are as reported by Roseberry. et al, in 1969-73.

continued next page

PRIMARY CORNER DESCRIPTION Sec. Cor. for 18 & 19; 13 & 24, T28-9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Coos County Surveyors Office - Michael Dado, Surveyor - Crew:  
 Matthew Martin & Bill Hales - 12/18/2014 - C.S. File 65/87-28  
 -----

Found - 3¼" brass cap on a 2½" iron pipe, 0.5' tall, in good condition and solid in the ground. There is a 1½" iron pipe painted orange touching the south side of said BCIP. For location help there is a 28" Hemlock North, 1.6'. Tree has a small Douglas Co. forest appraisal tag. 1972

A 44" D.Fir snag (dead) S.53°E., 24.19' to left side center. We find axe marks near the face, and 3 BLM tags in place. We paint a band around the tree in blue. Good Condition. 1855

A 5" dead Yew tree, N.77°E., 13.23' to right side center. We find visible scribes in partially healed face with a red and yellow Weyco. tag in place. We paint the face and a band around the tree in blue. Tree is in Poor condition and leaning hard to the left. 1962

An 18" hemlock, N.74°30'W., 14.47' to left side center. We find an off center healed blaze with both GP & BLM tags in place. We paint the face and a band around the tree in blue. Good condition. 1962

A 26" hemlock, S.21°W., 15.91' to right side center. We find a healed blaze with a BLM tag in place. We paint the face and a band around the tree in blue. Good condition. 1962

A 16" hemlock, S.52°E., 27.00' to left side center. We find visible scribes in a partly healed blaze & a BLM tag in place. We paint the face & a band around the tree in blue. Good Condition. 2003

A 12" hemlock, S.28°E., 17.39' t right side center. We find visible scribes in a partly healed blaze and a BLM tag (N.29°W., 17.4'; RD May 2001) in place. We find a BLM back tag in place. We paint the face and a band around the tree in blue. Good condition. Un-recorded.

A 56" D.Fir stump, S.6°W., 20.12' to heart center. We find no marks but there is a blank BLM tag in place. We paint the face in blue. Fair condition. Un-recorded.

New BO- An 11" yew stump, 2' tall, S.71°W., 44.39' to a steel spike and Coos County washer driven in at heart center. We chop an "X" in the face. We paint the "X" and the top of the stump in blue, and attach a yellow Coos County tag. Dec. 17°E