

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; S. 1, T28-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5786)

-----  
Set ¼ sec. post, from which  
    A Chinquapin 12" dia., bears S.85°W., 25 lks. dist.  
    A Chinquapin 12" dia., bears S.70°E., 56 lks. dist.

Survey by Floyd Vandervelden, LS #1047, Burnt Mt. Engineer - For: BLM - March 1982 - C.S. File 61/33-2

-----  
Found - A 12" Chinquapin bears S.70°E., 36 lks. (Orig. rec. 56 lks.), now a rotting snag with scribing clearly visible inside.

    A 12" Chinquapin bears S.85°W., 23 lks. scribing visible but very badly rotting log on the ground. (Orig. rec. 25 lks.)

New BTs- 7" Fir bears N.4°E., 9.1 ft. mkd. ¼ S BT.

    8" Fir bears S.89°30'W., 4.2 ft. mkd. ¼ S BT.

These trees also have a PK nail in them at the blaze with the letter W on them & each BT is painted red, has a BLM tag attached, a Weyerhaeuser tag attached & are also ribboned. A third Weyerhaeuser mkd. tree has been cut down and was a 10" Hemlock bearing N.57°E., 39.0 ft. with tag and PK nail.

Douglas County Surveyors Office - Gregory Quibell, Deputy - Karen Reed, crew - April 26, 1982 -C.S. File 61/30-27

-----  
Found - Orig. 12" now 14" Chinquapin snag 12 ft. tall. Fragmentary scribing "3" visible in previously opened face.

    Orig. 12" now 14" rotted Chinquapin windfall with reverse scribed BT visible on remains of stump. Scribed ¼ visible on rotted remains of tree.

    7" Fir with scribed ¼ S BT. As per previous ren.

    8" Fir with scribed ¼ S BT. As per previous ren.

    10" Hemlock stump. As per previous ren.

    The 7" Fir, 8" Fir and 10" Hemlock stump all have "W" nails & Weyerhaeuser BT tags.

I set a 1" x 30" I.P. with brass cap attached at record bearing and distance from the 14" Chinquapin windfall, N.85°E., 15.2 ft. (23 lks.). Cap mkd. "Douglas County Surveyor T28S R8W 1/4 S1 S6 R9W 1982"

    The 14" Chinquapin snag matches rec. for brg. (S.70°E.) but not for distance 23.8 ft. (36 lks.) Rec. 56 lks. If orig. notes have a 20 lk. error, then this tree would also match record.

(Cont. Next Page)

PRIMARY CORNER DESCRIPTION 1/4 cor. for Sec. 6; & S. 1, T28-9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

The two Fir BTs plus the 10" Hemlock stump mentioned by Vandervelden do not fit with this cor., but instead fit with a 1½" Fir stake which bears S.70°E., 8.4 ft. from set brass cap. I scratch "VOID" across existing BT tags on these trees.

New BTs-

- 7" Fir scribed "¼ SBT" bears N.53½°E., 11.0 ft. (scribing does not face cor.) (Vandervelden BT.)
- 8" Fir scribed "¼ S BT" bears S.54°E., 4.2 ft. (scribing does not face cor.) Vandervelden BT.
- 7" Fir scribed "¼ S1 CS BT" in double blaze bears N.28½°W., 6.3 ft.
- 8" Fir scribed "¼ S1 CS BT" in double blaze bears S.4°W., 18.1 ft.
- 10" Hemlock stump with "W" nail in face bears N.66°E., 45.0 ft.

Brushed line runs North & South out of corner. Line crossing tag South approx 500'. Dirt road is approx 60'± E of corner

BLM remonumentation by Aaron M. Graham, Cadastral Surveyor under Group #2012, surveyed April 2002/March 2003 - (DCSO rec. Vol. 54 Page(s) 21195-6)

-----

The ¼ sec. cor. of secs. 1 & 6, on the E. bdy. of the Tp., perpetuated by the Douglas County Surveyor's Office, in 1982, monumented with an iron post, 1" dia., firmly set, projecting 3" above the ground, with brass cap (properly) mkd. from which the remains of the original bearing trees

- A chinquapin, 12" dia., bears S.70°E., 24.1 ft., with illegible scribe marks visible on open blaze. (Record, 39.6 ft.)
- A root hole, bears S.85°W., 16.5 ft., with a chinquapin log, size indeterminate alongside, no marks visible.

and BTs mkd. by the Douglas County Surveyor's Office in 1982

- A fir, 13" dia. bears S.5½°W. 18.1 ft. with a healed blaze
- A hemlock, 12" dia. bears N.27°W. 6.2 ft with healed blaze

From this point, a point established as the ¼ sec. cor. of secs. 1 & 6, by Vandervelden, in 1982, bears S.73°17'00"E., 8.02 ft., determined by distance-distance intersection from BTs mkd. by Vandervelden. This point was erroneously positioned and is not utilized in this survey. From which bearing trees mkd. by Vandervelden.

- A fir, 13" dia. bears N.8¼°W., 9.1 ft. with a healed blaze
- A fir, 14" dia. bears S.83°W., 4.2 ft. with a healed blaze

and a bearing tree mkd. by person(s) unknown

- A hemlock stump, 9" dia., bears N.58°E., 39.3 ft., with no scribe marks visible on partially open blaze.