

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 19 and 30

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5823)

Set post 4 ft. long, 4" dia. 1 ft. in the ground for ¼ sec. cor., from which
A Laurel 24" dia., bears N.35°W., 10 lks. dist.
A Fir 72" dia., bears South, 37 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - Aug. 30, 1957 - C.S. File 49/12

Found two snags which I believe were the original BTs for ¼ corner.

The South, 24.4 ft. now 72" Fir snag, shows real old face and what I believe to be scribe marks "4 B", BT bark scribed.

The N.35°W., 6.6 ft. Laurel snag, shows real old face, center rotted, no scribe marks found. Now 24".

Bearing trees check for bearing and distances.

Set Brass cap at cor. mkd: County Surveyors Office

T 28 S R 8 W

¼ S 19

S 30

1957

New BTs- 12" Fir N.61°E., 13.7 ft. scribed ¼ S19 CS BT.

14" Fir S.62°E., 20.0 ft. scribed ¼ S30 CS BT.

Bruce Shaner - For: Superior Lumber Co. July 1993; M112-78 C.S. 63/153-19

Found 2½" Brass Cap properly marked on a 1" iron pipe from which:

20" W.Fir, (rec. 12") face overgrown, bears N.61°E., 13.7'.

24" W.Fir, (rec. 14") face overgrown, bears S.62°E., 20.0'.

72" D.Fir snag, no face or marks now visible, bears South 24.4' to face.

Laurel snag Orig BT. N.35°W., 6.6 ft. now gone.

New Accessories -

12" W.Fir, bears S.28°W., 28.3 ft. Scribed "¼ S30 BT"

8" W.Fir, bears N.3°W., 10.8 ft. Scribed "¼ S19 BT"

Corner is N.30°E., ± 500 ft. from end of old logging road to the west.