

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 18 and 19

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5826)

Set post 4 ft. long, 4" dia., 1 ft. in the ground for ¼ sec. post, from which
A Laurel 4" dia., bears S.60°E., 11 lks. dist.
A Hemlock 10" dia., bears N.15°E., 88 lks. dist.

Douglas Co. Surveyors Office - John M. Powell, and crew - April 20, 1970 - C.S. File 54/113-3

Looked for, not found.
BTs, one 10" Hemlock. No trace of anything. About 3" of snow.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15089)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 28 S R 8 W
1/4 $\frac{S 18}{S 19}$
1972

from which
A Fir 18" dia., bears N.15°W., 54 lks. dist. mkd. ¼ S18 BT
A Fir 24" dia., bears S.57°W., 68 lks. dist. mkd. ¼ S19 BT

BLM resurvey by A. Bert Skeesick Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2100, surveyed Sept. 2004 - (DCSO rec. Vol. 55 Page 21500) & 2008 BLM plat

The ¼ sec. cor. of secs. 18 & 19 monumented with an iron post 2½" dia., firmly set, projecting 3" above the ground, with brass cap mkd as reported by Roseberry, et al, in 1969-73; from which new BTs
A fir, 5" dia., bears S.49¾°W., 19.6 ft., mkd: ¼ S18 BT.
A hemlock, 6" dia., bears N.13¼°W., 19.6 ft. mkd: ¼ S18 BT
All new bearing trees have a 2½"x ¼" nail driven at the base on right side center.