

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 6 and 7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by George S. Pershin, under Contract #238, Dated, July 13, 1875 - (DCSO records Vol. 14 Page(s) 5829-30)

Set Fir post for 1/4 sec. cor., from which
A Fir 32" dia., bears N.8°E., 32 lks. dist.
A Chestnut 8" dia., bears S.43°W., 30 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - July/Aug. 1957 - C.S. File 49/5-6

Found - Orig. NE. BT now 40" Fir. I open old face and find scribing "S".

SW. BT, not found.

Set Brass cap at cor. mkd: County Surveyors Office

T 28 S R 8 W

1/4 S 6
S 7

1957

New BTs- 16" Ewood S.49°E., 20.2 ft. scribed 1/4 S7 CS BT.
8" Chinquapin N.27 1/2°W., 9.7 ft. scribed 1/4 S6 CSBT

Floyd Vandervelden, Burnt Mt. Engineer, BLM - March 1982 - C.S. File 61/33-2

Found - Orig. Fir BT, had fallen down and the bole subsequently logged.

The two new trees that Byron mkd. were in poor shape because the Chinquapin rotted completely away and the blazes and marks on the Yew tree were burned out due to the slash fire.

Found 1957 County brass cap.

New BTs- A 16" Yew bears S.49°E., 20.2 ft. mkd. 1/4 S BT using old burned out blazes.

A 14" Chinquapin bears N.32°15'W., 34.0 ft. mkd. 1/4 S BT.

Trees are painted red and marked with BLM BT tags.

Douglas Co. Surveyors Office - Gregory Quibell, Deputy - Karen Reed; Terry Plouff; John Powell, crew - April 22, 1982 - C.S. File 61/30-25

Found - 1957 DCSO brass cap, properly mkd., firmly set and protruding 2" out of ground.

Orig. 32" now 40" Fir which had fallen over and later logged. Root hole bears N.8°E., 21.1 ft., previously opened face was burned over and had no scribe visible.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 140600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 6 and 7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

	16" Yew now 16" snag approx. 30 ft. tall with burned out double blaze. Scribed "¼S BT" visible. Tree bears S.49°E., 20.2 ft.
	8" Chinquapin now 8" rotted stump with the remainder of the tree lying alongside also rotted, with scribed "4 S6 CS BT" visible in partially healed double blaze, bears N.30°W., 9.7 ft. (Rec. N.27½°W.)
	14" Chinquapin scribed "¼S BT" bears N.32°15'W., 34.0 ft.
New BTs-	19" Chinquapin scribed "¼ S7 CS BT" in double blaze, bears S.89°W., 107.6 ft.
	14" Fir scribed "¼ S6 CS BT" in double blaze, bears N.84½°E., 84.4 ft.