

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5812)

Set post cor. secs. 29, 30, 31 and 32, from which
A Fir 12" dia., bears N.46°W., 41 lks. dist.
A Fir 10" dia., bears S.42°W., 43 lks. dist.
A Fir 10" dia., bears S.58°E., 24 lks. dist.
A Fir 6" dia., bears N.2°E., 42 lks. dist.

H.L. Eppstein, Co. Surveyor - Wit: C. Martin; E. Edmonds; J. Frederickson - Nov. 5, 1924 - C.S. File 8/28; M 8-54

Set corner from old BT. Other BTs gone.
Marked new trees as follows:
Fir 12", bears N.50°W., 3.2 ft.
Fir 8", bears S.43°W., 7.8 ft.
Fir 8", bears S.16°E., 13.0 ft.
Fir 10", bears N.81°E., 4.8 ft.

BLM resurvey by John Jelley, Cadastral Surveyor, Group #552, surveyed July. 1964 - (DCSO records Vol. 32 Page(s) 13572)

The Sec. Cor., perpetuated and recorded by Eppstein, in 1924, from an original bearing tree which is no longer in existence, monumented with an iron pipe, 3/4" dia., 4" above ground, firmly set, from which bearing trees mkd. by Eppstein:

A Fir 14" dia., bears N.81°E., 8 lks. dist. with healed double blaze.
A Fir 11" dia., bears S.16°E., 20 lks. dist. with healed and partially opened double blaze.
A Fir 14" dia., bears S.43°W., 12½ lks. dist. with healed double blaze.
A Fir 19" dia., bears N.50°W., 5½ lks. dist. with healed double blaze.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 28 S R 8 W
S 30 | S 29
S 31 | S 32
1964

from which a new bearing tree:

A Fir 15" dia., S.33°E., 30 lks. dist. "T28S R8W S32 BT."

Reset Iron pipe alongside the iron post.

Corner is located at the end of a barbed wire fence, which extends South.

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 29, 30, 31 and 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM survey by Scott Toldness - PLS 90216 - Glahe & Associates
Professional Land Surveyors - 2024

Found - A 3¼" BLM brass cap on a 2½" iron post,
flush with ground, with a ¾" iron pipe along
N.E. face and a post N 0.7'.
A Fir 28" diam bears S.24½°E. 19.8' with healed
blaze and tag by CS0 64.
A Fir 22" diam bears S.8°E. 13.2' with healed
blaze and tag by BM 4/59.
A Fir 30" diam bears S.41¼°W. 8.25' with healed
blaze.
A Fir 31" diam bears N.34¾°E. 38.1' dist to nail at
left side center, scribed "T28SR8WS29BT" with LS
washer and tag by 90216 10/24.
New - Added paint, blazes, tags to re and replaced tags
with updated bearings.
Added post S. 5' and W.5'