

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 20 and 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5823)

Set post 4 ft. long, 4" dia., 1 ft. in ground for 1/4 sec. cor., from which

- A Fir 18" dia., bears N.10°W., 28 lks. dist.
- A Fir 20" dia., bears S.60°E., 28 lks. dist.

Douglas Co. Surveyors Office - James Byron and crew - Oct. 25, 1963 - C.S. File 52/79-16

Found - Orig. 20" now 36" Fir stump, S.60°E., 18.5 ft., shows reverse scribing.

Orig. 18" now 30" Fir stump, North 18.5 ft., not N.10°W., shows burned area that may have been old face.

Set Brass cap at cor. mkd: County Surveyors Office
T 28 S R 8 W

1/4 S 20
S 29
1963

New BTs- 23" Cedar bears S.29°E., 32.2 ft. scribed 1/4 S29 CS BT.

15" R.Fir bears N.35°W., 66.0 ft. scribed 1/4 S20 CS BT.