

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5826)

Marked a Fir 4" dia., for ¼ sec. post, from which
A Fir 46" dia., bears N.70°E., 76 lks. dist.
No other tree within reach.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15092)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T 28 S R 8 W
¼ $\frac{S \ 8}{S \ 17}$
1972

from which
A Fir 17" dia., bears N.13°E., 73 lks. dist. mkd. ¼ S8 BT
A Fir 10" dia., bears S.14°W., 15 lks. dist. mkd. ¼ S17 BT

Douglas Co. Surveyors Office - Randall Smith and Stephen Flause, crew - Aug. 9, 1984 - C.S. File 62/21-38

Found - 1972 BLM disk on a I.P. protruding 6" above ground properly mkd.
17" now 21" D.Fir 7 ft. high stump with a single well healed blaze, bears N.13°E., 48.2 ft.
10" D.Fir with a single well healed blaze, bears S.17°W., 9.7 ft. (Rec. S.14°W., is to center of trunk)
New BTs- 29" D.Fir double blazed and scribed "¼ S8 CS BT" bears N.49°W., 33.3 ft.
10" Hemlock double blazed and scribed "¼ S17 CS BT" bears S.28°E., 16.0 ft.
Corner lies on an East slope.

Survey by Howard W. Johnstone, LS #498 - For: Roseburg Lumber Co. - March 19, 1987 - C.S. File 63/26-2

Found - 1972 BLM resurvey brass cap in good condition.
22" Fir N.15°E., 48.2 ft., now a high stump, face overgrown.
(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 240500

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 17

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

10" Fir S.14°W., 9.9 ft., low stump, ½ face remains, overgrown.
29" Fir N.49°W., 33.3 ft., blaze open.
New BT - 7" Hemlock S.21°W., 40.7 ft. scribed "¼ S17 BT".
Placed brass tag on face, "LS 498"
In new clear cut unit. Timber is now cut on South and East sides of corner.

Douglas Co. Surveyors Office - Crew: Stephen J Flause & Mike Koch - Nov. 8, 2018 (Filed 11/17/2021) - C.S. File 67/50-5

Found - A 2½ o.d. iron pipe by Roseberry, Berry, Popken and Garrison, USBLM Cadastral Surveyors in 1972, firmly set, projecting 4" above the ground with a ¾" brass cap (properly) marked
BTs by Roseberry, Berry, Popken & Garrison in 1973 -
A 20"x6½' tall rotted D.Fir snag bears N.13°E., 48.2 ft. with a healed blaze.
A 11"x18" tall D.Fir stump bears S.17°W., 9.9 ft. with a healed blaze.
BTs by Smith, in 1984 -
A 30"x18" tall D.Fir stump bears N.49°W., 33.3 ft. with scribe marks "BT" visible on a partially healed blaze.
A 9"x12" tall rotted hemlock stump bears S.28°E., 16.0 ft.
BTs by Johnstone in 1987 -
A root hole bears S.21°W., 40.7 ft. with a uprooted hemlock alongside.
New - A 7" D.Fir bears N.74°E., 15.3 ft. scribed "¼ S8" "CSBT"
A 7" D.Fir bears S.41°E., 6.6 ft. scribed ¼ S17CS" "BT"
A 8" D.Fir bears S.19°W., 8.4 ft. scribed "¼S17" "CSBT"
A 8" D.Fir bears N.4°W., 4.0 ft. scribed "¼S8" "CSBT"
Note All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to a 2½" PK nail in the side and center of the root crown.
Compass declination 15°E.