

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5811)

Set post cor. secs. 28, 29, 32 and 33, from which
A Fir 20" dia., bears N.18°W., 30 lks. dist.
A Fir 12" dia., bears S.65°W., 19 lks. dist.
A Fir 24" dia., bears S.38°E., 56 lks. dist.
A Fir 36" dia., bears N.50°E., 37 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey, crew - Sept. 9, 1957 - C.S. File 49/12-11

Found all four original BTs. All BTs except NE. BT show good bark scribing. All check for bearing and distance.
The NW. Bt now 36" Fir stump.
The SW. BT now 24" snag.
The NE. BT now 40" stump, shows old face I do not open.
The SE. BT now 30" Fir, dead.

Set Brass cap at cor. mkd: County Surveyors Office
T 28 S R 8 W
S 29 | S 28
S 32 | S 33
1957

New BTs- 14" W.Fir N.78°E., scribed T28S R8W S28 CS BT.
12" Cedar, East 39.0 ft. scribed T28S R8W S33 CSBT
18" W.Fir S.21½°W., 19.9 ft. scribed T28S R8W S32 CS BT.
10" W.Fir N.36½°W., 44.0 ft. scribed T28S R8W S29 CS BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15577-78)

The Sec. Cor., perpetuated and recorded by Byron in 1957, monumented with an iron post 1½' dia., firmly set, projecting 10" above ground with brass cap mkd. in 1957

from which the remains of the original bearing trees:
A sawed Fir stump 38" dia., bears S.38°E., 56 lks. dist., with healed lower blaze, and a down log alongside, with fragmentary scribe marks visible on bark blaze.
A Fir stump 18" dia., bears S.61¼°W., 19 lks. dist., with healed lower blaze, and fragmentary scribe marks visible on bark blaze. (Rec. S.65°W.)
A sawed Fir stump 38" dia., bears N.19 3/4°W., 32 lks. dist., with fragmentary scribe marks visible on bark blaze. Rec. N.18°W., 30 lks.) (Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 300200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 28, 29, 32 and 33

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

and bearing trees mkd. by Byron:
A W.Fir 20" dia., bears N.72¼°E., 8 lks. dist., with healed blaze.
A Cedar 13" dia., bears N.87½°E., 60 lks. dist., with scribe marks T28S R8W S33 CS BT visible on open blaze.
A W.Fir 20" dia., bears S.20°W., 30 lks. dist., with healed blaze.
A W.Fir 16" dia., bears N.37¼°W., 67 lks. dist., with healed blaze.
and a new bearing tree:
A W.Fir 6" dia., bears S.33 3/4°E., 58 lks. dist., mkd. T28S R8W S33 BT.

Fd. OK, Dec. 11, 1989 by L. Roberts - M109-38; CS File 63/102

Mark Smalley - For: Roseburg Resources - 2/2002 - M139-54

Condition report only
Found - 1957 county brass cap on iron pipe
BTs - 29" W.Fir N.72¼°E., 5.3' healed.
17" Cedar N.87½°E 39.6' healed.
25" W.Fir S.20°W., 19.8' healed.
22" W.Fir N.37°W., 44.2' healed.
15" W.Fir S.33¾°E., 38.3' healed.
38" stump 4' Tall N.19¾°W., 21,1' rotten (OBT)
38" stump 2' Tall S.38°E., 37,0' rotten (OBT)
18" stump S.61¼°W., 12,5' rotten (OBT)

FD. BC & 5 BTs, by K. Hoffine - 1/2009 - M158-54