

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5818)

Set post 4 ft. long, 5" dia. and 1 ft. in ground for cor. of secs. 16, 17, 20 and 21, from which
A Fir 24" dia., bears N.40°W., 41 lks. dist.
A Fir 20" dia., bears S.68½°W., 46 lks. dist.
A W.Fir 24" dia., bears S.48°E., 46 lks. dist.
A W.Fir 36" dia., bears N.59°E., 40 lks. dist.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - Aug. 16, 1957 - C.S. File 49/12-2

Found - Orig. 24" Fir now 40", N.40°W., 27.1 ft. Bark scribed S17 R8W
Orig. 20" now 36" Fir, 30.4 ft. bark scribed.
The SE. and NE. original BTs not found.

Set Brass cap at cor. mkd: County Surveyors Office
T 28 S R 8 W
S 17 | S 16
S 20 | S 21
1957

New BTs- 14" W.Fir bears S.45°E., 11.0 ft. scribed S21 T28S R8W CS BT.
16" Cedar bears N.35½°E., 39.0 ft. scribed S16 T28S R8W CS BT.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15087-88)

The Sec. Cor., perpetuated and recorded by Byron in 1957, monumented with an iron pipe 2' dia., firmly set, protruding 8" above ground with brass cap mkd. in 1957, from which the remains of the original bearing trees:

A Fir 45" dia., bears S.68½°W., 46 lks. dist., with healed blaze.
A Fir stump 50" dia., bears N.40°W., 41 lks. dist., no marks visible.

and bearing trees mkd. by Byron:

A Cedar 25" dia., bears N.35°E., 59 lks. dist., with healed blaze.

A W.Fir snag 16" dia., bears S.45°E., 17 lks. dist. with scribe marks T28S R8W CS S21 BT visible on open blaze.

and new bearing trees:

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 300400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 16, 17, 20 and 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 11" dia., bears S.73°E., 24 lks. dist., mkd. T28S R8W S17 BT.
A Fir 12" dia., bears N.50°W., 61 lks. dist., mkd. T28S R8W S17 BT.

Cor. Fd. and used in BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15581-82)

BLM Retracement by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300, Surveyed Sept/Oct. 2009 - (DCSO records Vol. 56 Page(s) 22272-3)

The cor. of secs. 16, 17, 20, and 21, established by Chapman in 1875, perpetuated by Byron, in 1957, monumented with an iron post, 1¼" dia., firmly set, projecting 19" above ground, with brass cap (properly) mkd.

from which the remains of the orig. bearing trees
A sawed fir stump, 50" dia., bears S.66°W., 30.4 ft., with a healed blaze.

A sawed, decayed fir stump, size indeterminate, bears N.43½°W., 27.1 ft., with a healed blaze.

and the remains of BTs mkd. by Byron, reported by Jelley

A sawed cedar stump, 38" dia., bears N.35°E., 38.9 ft., with a healed blaze.

A decayed fir stump, size indeterminate, bears S.45°E., 11.2 ft., with no marks visible.

and BTs mkd. by Roseberry. Berry, Popken, and Garrison, reported by Jelley

A fir, 23" dia., bears S.73°E., 15.8 ft., with a healed blaze.

A fir, 29" dia., bears N.53½°W., 40.3 ft., with a healed blaze.

and new accessories

A fir, 6" dia., bears N.30½°E., 25.0 ft., mkd. T28S R8W S16 BT.

A rebar, 30" long, 5/8" dia., driven 28" in the ground for a reference monument, bears S.47°31'27"W., 19.38 ft. with an aluminum cap mkd. RM T28S R8W S20 19.4 FT TO COR 2009 and on arrow pointing to the corner.

Fd as per 2004 BLM renewal, David Edwards - Feb. 2012 - C.S. File 65/75-3