

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 8 and 9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5820)

Set post 4 ft. long, 4" dia., 1 ft. in ground, for ¼ sec. cor., from which
A Fir 15" dia., bears S.68°W., 10 lks. dist.
A Fir 18" dia., bears N.70°E., 19 lks. dist.

Survey by Marvin Ramsey - For: Southern Oregon Plywood - July/Aug. 1962 - C.S. File 51/242

39.84 ch. point for the ¼ cor. at proportionate distance. Find no evidence of the original corner.
Set an Iron pipe 3 ft. long, 1½" dia., 28" in the ground, from which
12" D.Fir bears S.84°E., 19 lks. mkd. ¼ S9 RS404 BT.
8" D.Fir bears S.9½°W., 16 lks. mkd. ¼ S8 RS404 BT.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15586)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼
S 8 S 9
T 28 S R 8 W
1975

from which
A Fir 6" dia., bears N.86½°E., 13 lks. dist. mkd. ¼ S9 BT
A Fir 6" dia., bears N.39°W., 40 lks. dist. mkd. ¼ S8 BT.

From this point, a local corner, established by Ramsey in 1962, bears N.59°20'E., 0.482 chs. dist., monumented with an iron pipe 1½" dia., firmly set, projecting 2" above ground, from which bearing trees mkd. by Ramsey:

Fir 14" dia., bears S.84°E., 19 lks. dist. with healed face.
A Fir 11" dia., bears S.9½°W., 16 lks. dist. with healed face.