

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 21 and 28

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5817)

Set post 4 ft. long, 4" dia. and 1 ft. in ground, for 1/4 sec. cor., from which
A W.Fir 10" dia., bears S.5°E., 26 lks. dist.
A W.Fir 10" dia., bears N.45°W., 42 lks. dist.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15083-84)

Point for the 1/4 sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:
T 28 S R 8 W
1/4 S 21
S 28
1973

from which
A Fir 11" dia., bears N.17°W., 43 lks. mkd. 1/4 S21 BT
A Fir 13" dia., bears S.37 1/2°E., 82 lks. mkd. 1/4 S28 BT.

Fd. OK, Aug. 1993 by D. Bentz - M 117-61
Found OK by D. Edwards, Jan. 2003 - M141-66

Mark Smalley, Roseburg Forest Products - Party Chief: William Olson - May 2009 - C.S. File 65/66-27

Found - 1973 BLM brass cap
13" Fir S.37 1/2°E., 82 lks Rotten stump 1973
15" Fir N.17°W., 43 lks Dead snag with healed face 1973
New - 15" D.Fir N.60°E., 25.6' measured to nail in the side-center of stump Scribed "1/4SBT" with LS 2354 brass washer
13" W.Fir S.62°W., 22.9' measured to nail in the side-center of stump Scribed "1/4SBT" with LS 2354 brass washer
18" D.Fir S.38°E., 45.4' measured to nail in the side-center of stump Scribed "1/4SBT" with LS 2354 brass washer
11" W.Fir S.52°E., 13.2' measured to nail in the side-center of stump Scribed "1/4SBT" with LS 2354 brass washer