

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 340400

PRIMARY CORNER DESCRIPTION 1/4 cor. for Secs. 16 and 21

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5818)

-----  
Set post 4 ft. long, 4" dia., 1 ft. in ground for ¼ sec. cor., from which  
A Fir 18" dia., bears S.70°W., 65 lks. dist.  
No other tree in reach.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #863, surveyed May/July 1975 - (DCSO records Vol. 38 Page(s) 15583)

-----  
Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

¼  $\frac{S\ 16}{S\ 21}$   
T 28 S R 8 W  
1975

from which

A Fir 17" dia., bears N.82°W., 45½ lks. dist. mkd. ¼ S16 BT.  
A Fir 16" dia., bears S.62°W., 31½ lks. dist. mkd. ¼ S21 BT.

Fd. OK, July 1993 by D. Bentz - M 112-80

BLM Retracement by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2300, Surveyed Sept/Oct. 2009 - (DCSO records Vol. 56 Page(s) 22272-3)

-----  
The ¼ sec. cor. of secs. 16 & 21, established by Chapman in 1875, reestablished by Jelley in 1975, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, with brass cap (properly) mkd.

from which the remains of bearing trees mkd. by Jelley

A sawed, burnt, decayed fir stump, 19" dia., bears S.62°W. 20.8 ft. with a healed blaze and a metal cover.

A decayed fir stump, size indeterminate, bears N.82°W., 30.0 ft., with fragmentary scribe marks visible on loose fragment.

and new bearing trees

A fir, 7" dia., bears S.79¼°W., 23.5 ft., mkd. ¼ S21 BT.  
A fir, 5" dia., bears N.2½°W., 10.9 ft., mkd. ¼ S16 BT.