

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 4 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5784)

Marked a Fir 4" dia. for ¼ sec. cor., from which
A Fir 10" dia., bears S.25°E., 20 lks.
A Fir 4" dia., bears N.30°E., 3 lks.

BLM Resurvey by C. Albert White; John M. Jelley; James E. Jelley, Cadastral Surveyors, Under group #466, Surveyed Sept/Oct. 1961 - (DCSO records Vol. 30 Page(s) 12861-62)

The standard ¼ sec. cor. of sec. 4, determined at record bearing and distance from the original SE. bearing tree:

A Fir 25" dia., bears S.25°E., 20 lks. dist., mkd. with an opened blaze, illegible bark scribing and Lecklider's cruiser mark. Reblaze and mark ¼ S4 SC BT.

A piece of Fir pitch face, 3" wide, 18" long, mkd. BT, was found lying beside the corner point. Lecklider asserts that this is the remainder of the original NE. bearing tree.

and a tree mkd. by Boyer, RPE 1581:

A Hemlock 10" dia., bears N.67°W., 20 lks. dist., mkd. ¼ S4 and other illegible scribe marks on a partially overgrown face.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, to solid rock, and in a mound of stone, 3 ft. base, to top, with brass cap mkd:

¼ S 4
T 28 S R 8 W
S C
1961

from which a new bearing tree:

A Hemlock 6" dia., bears S.38°W., 35 lks. dist. mkd. ¼ S4 SC BT.

Douglas Co. Surveyors Office - V.R. Tracy, and crew - May 18, 1970 - C.S. File 54/113-15

Found - 1961 BLM brass cap, properly set and marked.
Orig. 25" Fir, alive, S.25°E., 13.2 ft., rescribe visible on unhealed blaze.
10" Hemlock N.67°W., 13.2 ft., blazes nearly healed.
We tag. (Boyer's BT)
6" Hemlock broken off 15 ft. high, dying, S.38°W., 23.1 ft. scribe visible.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 340700

PRIMARY CORNER DESCRIPTION No. 1/4 Cor. for Sec. 4 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BT - 7" Hemlock S.44°W., 20.8 ft. mkd. ¼ S4 SC CS BT.
Corner lies on top of spur, sloping W.
The ¼ cor. of sec. 33, T27½-8, bears N.89½°E., 27.1 ft.

Fd. OK Dec. 1996 by R. Hintz - M 103-8

BLM rehabilitation of a corner by Timothy J. Moore, Cadastral Surveyor & Robert H. Browning, Surveying Tech. under Group #2000, surveyed Oct. 2007 (DCSO rec. Vol. 55 pg(s) 21596-7)

The standard ¼ sec. cor. of sec. 4 only, monumented with an iron post, 2½" dia., firmly set, projecting 12" above ground, in a collar of stone, 2½ ft. base, 6" high, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A fir snag, 25" dia., bears S.18°E., 13.2 ft., with scribe marks ¼ S4 SC BT visible on open blaze. (Rec. S.25°E.) and the remains of a BT mkd. by Boyer, reported by White, Jelley, and Jelley

A sawed hemlock stump, 10" dia., bears N.67°W., 13.2 ft., with no scribe marks visible on open blaze.

and the remains of a BT mkd. by White, Jelley, and Jelley

A hemlock snag, 5" dia., bears S.38°W., 23.1 ft., with a healed blaze.

and new bearing trees

A fir, 6" dia., bears S.81¾°W., 16.7 ft., mkd. ¼ S4 SC BT.

A hemlock, 18" dia. bears N.12¾°W. 4.3 ft. mkd. ¼ S4 SC BT