

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by W. S. Chapman, Deputy Surveyor, under Contract #234, dated June 24, 1875 - (DCSO records Vol. 14 Page(s) 5814-15)

Set post 4 ft. long, 4" dia., and 1 ft. in ground for ¼ sec. cor., from which
W. Fir 15" dia., bears S.88¼°E., 45 lks. dist.
Fir 12" dia., bears N.53°W., 7 lks. dist.

BLM Resurvey by Lynn Roseberry; Daniel Berry; Gordon Popken and Albert Garrison, Cadastral Surveyors, under Group #'s 691 and 764, Surveyed June, 1969/April 1973 - (DCSO records Vol. 36 Page(s) 15081)

Point for the ¼ sec. cor., at proportionate distance; there is no remaining evidence of the original corner.
Set an iron post, 28" long, 2 1/2" dia., 22" in the ground, with brass cap mkd:
T 28 S R 8 W
1/4
S 9 | S 10
1969

from which
A Fir 10" dia., bears N.28°E., 71 lks. dist. mkd. ¼ S10 BT
A Fir 8" dia., bears N.44½°W., 118 lks. dist. mkd. ¼ S9 BT
Corner falls in dirt road, 15 lks. wide, bears E. and W. and 3 lks. W. of creek, course S.15°W.

Fd. & used in BLM resurvey by Boyd W. Peterson, under Group #1364, Surveyed May/Aug 1987 - (DCSO records Vol 48 PG 18406)

David Edwards - For: Roseburg Resources - 11/2003 - M 143-25

Found - BLM brass cap
22" Fir N.28°E., 46.9'
14" Fir N.44½°W., 77.9'
Both w/healed blazes
11" Fir N.66°E., (no dist. taken) (no rec.)
8" Fir N.55°W., 46.9' (no rec.)
Both w/scribing visible & RFP tags.