

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5806)

Set ¼ sec. post, from which
A Fir 18" dia., bears South, 20 lks. dist.
A Cedar 36" dia., bears N.17°E., 16 lks. dist.

H.L. Eppstein, Co. Surveyor - Wit: Harley Johnson; B.A. Lane; G.C. Sellers - March 4, 1930 - C.S. File 14/58; Vol. 4 Pg. 9

Set a Yewwood post from old BT, a 36" Cedar.
Marked new witness trees:
W.Fir 6" dia., bears N.65°W., 14.0 ft.
R.Fir 14" dia., bears S.80°E., 19.2 ft.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - Aug. 27, 1957 - C.S. File 49/12-3

Found - Scribe YewWood post 4x4x20" long, scribed ¼S11 CS 2 Cedar tree, now 48" dia., N.18°E., 10.7 ft., face not completely grown over showing scribe "¼ S2 CS". Does not appear old enough for original, probably refaced and rescribed by Eppstein in 1930.
10" W.Fir N.55°W., 13.8 ft., showing 2 good scars.
22" D.Fir S.77°E., 19.2 ft. showing 2 good scars. I did not chop out scar on either of these trees.
All trees are alive and apparently in good condition except that W.Fir is partly uprooted and leaning badly.
Corner post is in a fairly new E-W fence line.
Set an iron pipe at corner, with brass cap stamped: County Surveyors Office 1957 ¼ S 2 S 11 T28S R8W.

BLM Resurvey by Dale T. Bedell, Cadastral Surveyor, under Group #1278, Surveyed July/Oct. 1985 - (DCSO records Vol. 48 Page(s) 18252)

The Sec. Cor., perpetuated and recorded by Eppstein in 1930, and further perpetuated and recorded by Byron in 1957, monumented with an iron post, 1½" dia., projecting 6" above ground with cap mkd. in 1957
from which the remains of an original bearing tree
A Cedar stump 62" dia., bears N.17°E., 18 lks. dist., with reverse scribe marks ¼ S2 visible on overgrowth. (Rec. 16 lks.)
and the remains of the bearing trees mkd. by Eppstein:
(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 540600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 2 and 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A Fir 28" dia., bears S.78°E., 30 lks. dist., with healed double blaze.
A root hole bears N.55°W., 21 lks. dist., with a rotted Fir log, 15" dia., lying alongside, with healed double blaze.
and a new bearing tree
A Fir 11" dia., bears N.47°W., 52 lks. dist., mkd. ¼ S2 BT.
Corner is located in a wire fence line, bearing E. and W.

Fd. Ok by Gary Smithers, June 2007 - M153-42