

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5798)

-----  
Set post cor. secs. 13, 14, 23 and 24, from which  
An Oak 20" dia., bears S.82°E., 45 lks. dist.  
An Oak 10" dia., bears N.70°E., 46 lks. dist.  
An Oak 20" dia., bears N.17°W., 54 lks. dist.  
An Oak 30" dia., bears S.47°W., 96 lks. dist.

Arthur Boyer, Douglas Co. Surveyor - Wit: Fred Kiehn; Elmer Bushnell - Oct. 7, 1939 - C.S. File 16/55 (and "old" cor. book, Pge 117)

-----  
Renewed from stumps:  
20" Oak stump, N.17°W., 54 lks.  
Stump of 30" oak, S.47°W., 96 lks.  
Stump hole 20" Oak S.82°E., 45 lks.  
Marked new bearing trees:  
Fir 10" dia. N.1°W., 4.0 ft. mkd. S14 T28S R8W CS BT.  
Fir 15" dia. N.85°E., 17.0 ft. mkd. S13 T28S R8W CS BT.  
Fir 18" dia. S.72½°E., 8.0 ft. mkd. S24 T28S R8W CS BT.  
Fir 8" dia. S.30°W., 22.5 ft. mkd. S23 T28S R8W CS BT.

Douglas Co. Surveyors Office - James Byron, Deputy - Milo Godfrey; J. Fee, crew - Aug. 29. 1957 - C.S. File 49/12-6

-----  
Found all four BTs as renewed by Boyer, 1939. NW. BT partly open, scribing visible. All other BTs have closed faces. I do not open. All BTs alive and in good condition and all check for bearing and distance.

Set Brass cap at cor. mkd: County Surveyors Office  
T 28 S R 8 W  
S 14 | S 13  
S 23 | S 24  
1957

No new BTs.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Sept. 1964 - C.S. File 52/79-14

-----  
Found - No trace of 1957 brass cap.  
Two of the four BTs are dead. Other BTs are turned out and slid down hill. Dead BTs as below:  
8" Fir S.40°W., 22.5 ft. recorded as S.30°W., shows scribe marks and is an snag.

(Cont. Next Page)

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

15" Fir N.85°E., 17.0 ft. is a stump and has a  
healed over face, visible on top.  
Set Brass cap at cor. mkd: County Surveyors Office  
T 28 S R 8 W  
S 14 | S 13  
S 23 | S 24  
1964  
New BTs- 9" D.Fir S.53°W., 59.5 ft. mkd. T28S R8W S23 CS BT.  
14" D.Fir N.55°E., 14.4 ft. mkd. T28S R8W S13 CS BT.  
10" D.Fir S.8°E., 56.6 ft. mkd. T28S R8W S24 CS BT.  
No tree available to NW.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under  
Group #863, surveyed May/July 1975 - (DCS0 records Vol. 38  
Page(s) 15570-71)

-----  
The Sec. cor. perpetuated and recorded by Boyer in 1939,  
further perpetuated by Byron in 1957, and further perpetuated  
and recorded by Byron in 1964, monumented with an iron post  
1½" dia., firmly set, projecting 10" above ground, with brass  
cap mkd. in 1964  
from which the remains of the original bearing trees:  
A root hole bears S.82°E., 45 lks. dist. with decayed  
remains of Oak stump in hole, no marks visible.  
A root hole, bears S.47°W., 96 lks. dist.  
and the remains of bearing trees mkd. by Boyer:  
A sawed Fir stump 16" dia., bears N.85°E., 26 lks. dist.,  
with healed blaze.  
A root hole bears S.72½°E., 12 lks. dist. with a down Fir  
alongside, 18" dia., with fragmentary scribe marks  
visible on open blaze.  
A Fir snag 9" dia., bears S.37½°W., 34 lks. dist., with  
fragmentary scribe marks visible on open blaze.  
A root hole bears N.1°W., 6 lks. dist. with a down Fir  
alongside, 10" dia., with fragmentary scribe marks  
visible on open blaze.  
and the remains of bearing trees mkd. by Byron:  
A Fir snag 13" dia., bears N.60½°E., 23 lks. dist., with  
scribe marks T28S R8W S13 CS BT visible on open blaze.  
A Fir 16" dia., bears S.4°E., 85½ lks. dist., with healed  
blaze.  
A Fir 15" dia., bears S.57°W., 92 lks. dist., with scribe  
marks T28S R8W S23 CS BT visible on open blaze.  
and a new bearing tree:  
A Fir 6" dia., bears N.76½°W., 51½ lks. dist. mkd. T28S  
R8W S14 BT.

continued next page

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 600400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13, 14, 23 and 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Mark Smalley - For: Roseburg Resources - 7/2001 - M 138-50 ----- Found - 1964 County brass cap on iron pipe. 21" (16") Fir S.4°E., 56.4' healed. 20" (15") Fir S.57°W., 60.7' healed. 19" (6") Fir N.76½°W., 34.0' healed. Scribed- 15" Fir S.79°w., 32.2' "S 23 BT"
FD. Ok by D. Edwards, 8/2009 - M159-62 Fd. BC & accessories by R. Quimby, 4/2013 - M157-71