

TOWNSHIP 28 RANGE 08 POINT IDENTIFIER # 640600

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 12

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO records Vol. 14 Page(s) 5800)

Set ¼ sec. post, from which
A Fir 40" dia., bears N.49°E., 38 lks. dist.
A Chinquapin 8" dia., bears S.27°W., 23 lks. dist.

Survey by Marvin C. Ramsey - For: J.H. Baxter & Co. - File Jan. 26, 1960 - C.S. File 51/65

Determined from original BTs:
D.Fir stump 44", bears N.49°E., 38 lks. mkd. B with other marks burned out.
36" Chinquapin bears S.27°W., 23 lks. dist. with axe face, marks decayed.
Set Iron pipe 3 ft. long, 1½" dia., 28" in the ground mkd. RS404, from which new bearing trees:
8" W.Fir bears N.55°E., 15 lks. dist. mkd. ¼ S1 RS404 BT.
10" D.Fir bears S.57°E., 18 lks. dist. mkd. ¼ S12 RS404 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - July 1966 - C.S. File 52/79-25

Found - 1½" I.Pipe at corner.
Orig. 36" Chinquapin, now broken off snag, S.27°W., 15.2 ft., no scribe visible.
No trace of 44" Fir stump, N.49°E., 25.1 ft.
10" D.Fir S.57°E., 11.9 ft., healed over face, scribe marks visible.
8" W.Fir N.55°E., 9.9 ft. Tree down, scribe visible.
New BT - 11" W.Fir N.69°W., 9.8 ft. scribed ¼ S1 CS BT.
Corner lies on top of ridge, running East and West. yellow tag on road 500 ft. West of ¼ corner.

Fd. OK, Nov. 1985/Jan. 1986 by R. Geisler - M 90-79