

PRIMARY CORNER DESCRIPTION North 1/4 Cor. for Sec. 1 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Dennis Hathorn, Deputy Surveyor under Contract #57, dated April 12, 1855 - (DCSO rec. Vol. 14 Page(s) 5783)

Set ¼ sec. post, from which
A B.Oak 36" dia., bears S.26°E., 339 lks.
A W.Oak 24" dia., bears N.87°E., 331 lks.

GLO survey by Wm. P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO rec Vol. 13 Page 5277)

S C 1/4 sec. cor. sec. 1 by both sets of chainmen (original position of post established from witness trees as described by Surveyor General.)

Survey by Marvin C. Ramsey - For: J.H. Baxter & Co. - Filed Jan. 26, 1960 - C.S. File 51/65

Found original BTs:
A W.Oak 30" dia., bears N.87°E., 331 lks., with BT scar decayed. I open top scar & find axe face, marks decayed.
A B.Oak 44" dia., bears S.26°E., 339 lks. down & charred by slash fire.
Set Iron pipe 3 ft. long, 1½" dia., 28" in the ground, mkd. RS404, from which
18" Cedar bears S.78°E., 70 lks. dist. mkd. ¼ S1 RS404 BT.
38" Cedar bears S.36°W., 87 lks. dist. mkd. ¼ S1 RS404 BT.

Fd. OK, March 1975 by V. McLind - M 55-57

Survey by Ronald G. Geisler, LS #1988 - For: Champion International Corp. - Nov. 1985/Jan. 1986 - M 90-79

Found - 1960 1½" Iron pipe set by Ramsey.
31' W.Oak bears N.87°E. 218.5 ft. rotted face, orig.
44" B.Oak, down and decaying. Original.
50" Cedar bears S.36°W., 63.3 ft. (Rec. 57.4 ft.)
Closed face. (1960 BT)
New BT - 14" B.Oak bears S.24°E., 101.6 ft. scribed N ¼ S1 BT

Tony Hostetter - For: Seneca Jones Tmbr - Aug. 2002 - M140-72

Found - 1½" iron pipe & BTs as described by Geisler
New BTs- 22" Fir scribed "S1 ¼ BT" bears N.42°E., 50.7 ft. to spike.
20" Oak, scribed "S1 ¼ BT" bears N.4°E., 73.5 ft. to spike.