

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Original - Dennis Hathorn, Deputy, Contract #57 dated April 12, 1855 (DCSO records, Vol. 14 Page 5790)

(At 40.00 chains, 1/4 sec. cor. Ground so rocky that a post could not be driven.)

(At 40.43 chs) Marked a W.Oak 3" dia., for Witness Corner to true corner, from which

A W.Oak 6" dia., bears N.48°E., 37 lks. dist.

A W.Oak 10" dia., bears S.75°W., 73 lks.

GLO resurvey by Mensch, 1924 (DCSO records, Vol. 14 Page 5917)

Point for 1/4 sec. cor., located 43 lks. North of the witness 1/4 sec. cor., (hereafter described)

At the true cor. point, which falls on solid bedrock covered with 6" of soil, I mark a cross (X) 1/4 on the bedrock, over which set a basalt stone, 20 x 12 x 6 ins., surrounded with a mound of stone and earth, for 1/4 sec. cor. marked 1/4 on W. face; from which

A B.Oak 8" dia., bears S.15°E., 39 lks. dist. mkd. 1/4 S19 R7 1/2 BT.

A B.Oak 8" dia., bears S.28°W., 30 lks. dist., mkd.

1/4 S 24 BT.

Intersect the point for the Witness Corner to the 1/4 sec. cor., located by record bearing and distance from the orig. SW BT, which is a B.Oak snag, bears S.75°W., 73 lks. dist., marks still legible. The NE BT has fallen, but the marks are still legible. The Witness Corner is not restored.

Doug. County Surveyors Office - James W. Byron, Deputy - Milo Godfrey; Clete Putnam - May 1961 - C.S. File 52/79-9

Found - Both BTs, each shows good scars but have rotted centers.

Find stone at corner but do not find "+" nor any marks.

We drill hole in rock and set 1/2" x 12" I.Rod at corner and 3/4" x 30" I.Rod alongside rods set in concrete.

New BTs -6" W.Oak bears S.22°W., 20.5 ft. scribed 1/4 S24 CSBT

7" W.Oak bears S.58°E., 22.0 ft. scribed 1/4 S19 CSBT.