

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 401100

PRIMARY CORNER DESCRIPTION CC Sec. 3 & 4, North; T30-1E

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Cadastral Engineer, under special instructions Dated June 7, 1922 - (DCSO records Vol. 25 Page 10680 & Vol. 26 Page 10984)

Set a conglomerate stone 24x14x10", 18" in the ground, for closing cor. of secs. 3 & 4, mkd with 3 grooves on E, CC & 6 grooves on S & 3 grooves on W face; from which
A fir, 20" dia., bears S.10°E., 50 lks., mkd: T30S R1E S3 CC BT.
A fir, 10" dia., bears S.45°W., 22 lks., mkd: T30S R1E S4 CC BT.
No iron post available for this corner.

GLO resurvey by Norman D. Price, Cadastral Engineer, Leonard Carter, Public Land Surveyor, and George F. Dawson Jr., Transitman, under Group No. 175 surveyed April/Aug. 1937 - (DCSO records Vol. 34 Page(s) 14077)

Set an iron post, 3 ft. long, 2" dia., 27" in the ground, with the orig. stone deposited at the base, for closing cor. of secs. 3 & 4, with brass cap mkd
T29S R1E
S 34
S 4 | S 3
T30S R1E
C C
1937

from which
A fir, 15" dia., bears S.10°E., 49 lks., blaze healed; I do not open (Old BT)
A dead fir, 10" dia., bears S.45°W., 22 lks., mkd. T30S R1E S4 CC BT. (Old BT)
A fir, 40" dia., bears S.36°W., 70 lks., mkd. T30S R1E S4 CC BT. (New BT)

Douglas Co. Surveyors Office - Larry E. Monrean - P. Earle - Oct. 6, 1976 - C.S. File 59/24-26

Found - 1937 GLO Brass properly stamped.
Orig. stone marker at base of brass cap.
A 15" now 18" Fir, bears S.10°E., 33.0 ft. (rec. 32.3 ft) Tree has well healed blaze.
A 40" Fir, bears S.36°W., 46.2 ft. Tree has well healed blaze.
A 10" Fir, bears S.45°W., 14.5 ft. in now broken off. (Tree dead in 1937) Tree has scribing "T30S R1E S4 CC BT"