

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract No. 797, dated April 19, 1910 - (DCSO records Vol. 25 Page(s) 10587)

-----

Set a conglomerate stone 15x10x8", 10" in the ground for ¼ sec. cor. mkd. ¼ on N face, from which

A hemlock, 15" dia., bears N.86°E., 15 lks., mkd: ¼ S27 BT

A hemlock, 6" dia., bears S.29°E., 8 lks., mkd: ¼ S34 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - 10/17/1974 - C.S. File 57/8-14

-----

Found - A conglomerate stone, firmly set flush with the surface of the ground and marked with a "¼" chiseled on the north face. from which:

An orig. 15" now 18" hemlock bears N.86°E., 9.9 ft. scribe marks visible on a nearly healed blaze.

An orig. 6" now 7" Hemlock bears S.29°e., 5.3 ft. alive and well healed.

Note - This corner lies on a very steep north slope.

Dennis Gaylord, USFS & Deputy Co. Surveyor - Witness: Chuck LeBold & Joe Sheriff - Feb. 10, 1977 - C.S. File 59/29-27

-----

Found - 12"x6"x5" stone set solidly in place, 2" above ground mkd "¼" on North face.

An 18" Hemlock, bears N.86°E., 10.1 ft. with healed scar.

A 7" Hemlock bears S.29°E., 5.3 ft. with healed scar.

Both BTs have county BT signs and are alive.

Set - Brass cap set in a mound of stone 2' at base x 2' high, mkd: Douglas County Surveyors T 29 S  
Office ¼ S 27  
1977 S 34  
R1E

Orig. corner stone buried alongside brass cap.  
Did not mark new BTs.  
Compass Declination: 22°30'E