

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 440500

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 15 (WC)

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 25 Page 10652)

N.89°52'W., on true line, bet. secs. 10 & 15
28.75 chs. Left bank of South Umpqua River
39.88 chs. South Umpqua Falls, 10 ft. high; true point for
1/4 sec. cor. in river
41.75 chs. Right bank of river, bears SW, asc. 35 ft. on SE
slope to
44.45 chs. Set an iron post, 3 ft. long, 1" dia., 27" in the
ground, for 1/4 sec. cor., with brass cap marked
1/4 S 10 WC
S 15
1921

from which

A fir, 12" dia., bears N.83°W., 13 lks., mkd: WC 1/4 S10 BT.

A fir, 18" dia., bears S.71°W., 66 lks., mkd: WC 1/4 S15 BT.

Douglas Co Surveyors Office - Gary Langlitz - Clell Goodwin -
A Vic Cangie - M Lenora Ladig - 9/4/1975 - C.S. File 57/36-4

Found - Iron pipe with brass cap attached and marked as
described in the official record.

This pipe is loosely set, extending approx. 18"
above ground and oriented in the wrong direction.
There is no evidence of the record BTs at this
location.

This corner lies approx 500 Ft. west of South Umpqua
Falls (Record, West 301.6 ft.) and approx 50'
north of the right bank of the river.

**Due to lack of evidence and conflicting calls, we do not
monument.**