

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 440600

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Cadastral Engineer, Group No. 62, dated Dec. 21, 1920 - (DCSO records Vol. 25 Page 10655)

-----  
Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4  $\frac{S \quad 3}{S \quad 10}$   
1921

from which

A fir, 18" dia., bears N.42°E., 25 lks., mkd: 1/4 S3 BT.

A cedar, 9" dia., bears S.28°E., 30 lks., mkd: 1/4 S10 BT.

-----  
Douglas Co. Surveyors Office - Gary Langlitz - Peter Earle - 8/5/1974 - C.S. File 57/2-11

-----  
Found - 1921 US GLO Brass cap properly marked. This monument was found sitting nearly out of the ground. Slightly bent and disoriented. The area around the corner has been logged some years ago.

We find a 20" D.Fir stump. 4 ft. tall, badly deteriorated which we open and find good scribing "1/4 S3 BT".

Reset - Brass cap at the record bearing and distance from the only remaining bearing tree:

An orig. 18" Fir, now 20" stump, bearing N.42°E., 16.5 ft.

New BTs - 7" Ponderosa Pine, bears N.22°W. , 17.2 ft. scribed "1/4 S3 CS BT".

4" Sugar Pine, bears S.35 1/2°W., 41.7 ft. scribed "1/4 S10 CS BT".