

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 640200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 25 & 36

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Fred Mensch, US Deputy Surveyor, under contract No. 797, dated April 19, 1910 - (DCSO records Vol. 25 Page(s) 10579)

A pine, 36" dia, for ¼ sec. cor. I mark ¼ S 25 on N & 36 on S side, from which

A cedar, 16" dia., bears N.53°W., 28 lks., mkd: ¼ S25 BT.

A fir, 20" dia., bears S.20°E., 61 lks., mkd: ¼ S36 BT.

Douglas Co. Surveyors Office - Gary Langlitz - Pete Earle - Oct. 3, 1974 - C.S. File 57/8-7

Found - The orig. corner tree, an orig. 36" now 32" Ponderosa Pine, with scribing ¼ S 25 plainly visible on the north face and scribe marks visible on a partially healed scar on the south side. This tree is in good condition.

We also find the two orig. bearing tree in good condition:

An orig. 16" now 21" Incense cedar bears N.53°W., 18.5 ft. well healed.

An orig. 20" now 26" D. Fir, bears S.20°E., 40.3 ft. well healed