

PRIMARY CORNER DESCRIPTION Cor. No. 20 HES 143 (2 WC's)

Alias	Description

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12023)

From Cor. No. 19 - S.70°07'E., 2.76 chs to WC
WC to cor. 20, HES 143, true point for this cor. which should be set at 3.36 chs., falls in bed of Rock Creek; I set a wash boulder, 24x10x8" 14" in the ground, for WC to Cor. 20 HES 143, mkd. WC on SE face, 20 HES 143 on SW face with a cross (+) on top; from which
 A fir, 6" dia., bears N.77°30'W., 48 lks.
 A fir, 6" dia., bears N.67°25'W., 50 lks.
 Both trees blazed and scribed WC 20 HES 143 BT.
Pits & mound impracticable at this and all other cors.
3.36 chs. point for cor. 20, HES 143 in Rock Creek
From true point for Cor. 20
S.6°55'E., on true line to Cor. No. 21, 0.94 chs
WC to Cor. 20 HES 143
At this point, I set a wash boulder, 24x12x8", 14" in the ground, for WC to Cor. 20, HES No. 143, mkd. WC on NW face, 20 HES 143 on SW face, with a cross (+) on top; from which
 A fir, 6" dia., bears S.5°30'W., 24 lks.
 A fir, 7" dia., bears S.30°15'W., 9 lks.
 Both trees blazed and scribed WC 20 HES 143 BT.
Pits & mound impracticable at this and all other cors.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - 12/16&17/1969 - C.S. 54/82-99 & 100

(Westerly WC)
Found - Corner Stone, in place, mkd: "WC 20 HES 143".
 Orig. 6" Fir, now 18" stump, N.67½°W., 33.0 ft., open & find scribe.
 Other Orig. BT. gone.
Set - Brass Cap at Cor. mkd:
 County Surveyors T29S R1E
 Office, 1969 Wit.Cor → Cor.#20 HES 143
 True Cor. bears S.70°07'E. 39.6 ft. in creek.
New BTs- 8" W.Fir N.34°W. 31.2 ft. mkd: "WC 20 HES 143 CS BT"
 10" W.Fir N.74°W. 27.1 ft mkd: "WC 20 HES 143 CS BT"
This corner lies on flat in dense, vine maple brush. True Cor. S.70°07'E. 39.6' The rec distance btwn. Cors. #20 & #21 is 8.96 chs. On govt. plat, the same line shows 6.98 chs. In pacing I find the 6.98 chs to be more correct. Also the remains of the orig. listing corner would bear out this same location. A blazed stump bears S.81½°E. 15.6 ft., open & find obliterated blaze, also remains of scribe on a stump to S.E. facing corner, also obliterated. continued next page

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 943200

PRIMARY CORNER DESCRIPTION Cor. No. 20 HES 143 (2 WC's)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

(Southerly WC)
Found - Corner Stone, in place, with "20 HES" on broken pieces.
 Orig. 7" Fir, now 20" burned stump, S.30¼°W. 5.9 ft., we open & find "WC 2" scribe & reverse.
 No trace other Orig. ET.
Set - Brass Cap at Cor. MKd (Reset Pieces of Stone Alongside)
 County Surveyors T29S R1E
 Office, 1969 Wit. Cor. Cor.#20 ↑ HES 143
New BTs- 7" Hemlock N.58°W. 14.9 ft. mkd: WC 20 HES 143 CS BT
 10" D.Fir N.15°E. 52.0 ft. mkd: "WC 20 HES 143 CS BT
The true corner #20 bears N.6°55'W. 62.0 ft. in creek

Fd. both WC BCs - M. Farr, USFS - July 1975 - M56-26