

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 943230

PRIMARY CORNER DESCRIPTION Cor. No. 23 HES 143

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914- DCSO records Vol. 28 Page(s) 12024)

Cor. No. 23, identical with Cor. H/7. of listing survey No. 6-590 Tract 3, a post mkd. and witnessed as described by the listing surveyor, in place of which I set a porphyry stone, 24x12x6", 14" in the ground, for Cor. 23, mkd. 23 HES 143 on SW face with a cross (+) on top; from which

- A hemlock, 8" dia., bears S.89°00'E., 43½ lks.
- A fir, 6" dia., bears S.63°15'E., 24 lks.

both trees blazed and scribed 23 HES 143 BT.
Pits & mound impracticable at this and all other cors

Looked for/not fd. DCSO VRT 12/1969 - C.S. 54/82-101:
Destroyed by cat logging - No OBTs or cor. stone fd.

Maurice E. Farr, USFS - July 1975 - M56-26

Set - 1"x36" galv. pipe with Brass cap stamped "T29S HES 143 22 23 BO PE 5188 R1E 1975" from which bears:

- A 9" fir S.34°W., 29.8 ft scribed BO 22 & 23 HES 143 BT
- A 13" Fir N.68°30'E., 25.0 ft. scribed BO 22 & 23 HES 143 BT.

BTs reference only bearing object, bearing object is 38.0' S66°10'E., from Corner 23.

1