

PRIMARY CORNER DESCRIPTION Cor. No. 26 HES 143

Alias	Description
Alias	Description
Alias	Description
Alias	Description

HES No. 143 by Frank D. Maxwell, surveyor (FS), under special instructions dated April 27, 1914 - Surveyed June 1914 - DCSO records Vol. 28 Page(s) 12025)

-----  
Cor. 26, identical with Cor. H/21 of listing survey 6-97, a fir tree, 26" dia., mkd. & witnessed as described by the listing surveyor; I mark tree 26 HES 143 on W face, with a blaze on NE & SW faces, for cor. 26; from which  
A fir, 26" dia., bears N.1°30'E., 15½ lks.  
A fir, 26" dia., bears S.55°00'E., 31 lks.  
both trees blazed and scribed 26 HES 143 BT.  
Pits & mound impracticable at this and all other cors.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage & V. Perron - 12/17/1969 - C.S. File 54/82-103

-----  
Found - Stump of Orig. 26", now 32" Fir Corner Tree, shows good scar.  
Orig. 26" Fir, now 32" Stump, S.55°E. 20.5 ft., open & shows scribe.  
Orig. 26" Fir, now 30" Stump, N.1½°E. 10.2 ft., shows good scar.  
At a Point 2.0 ft. west of center of Corner Stump Set:  
Brass Cap at Cor. Mkd: County Surveyors T29S R1E  
Office, 1969 Cor.#26 (HES 143  
New BTs- 9" Maple S.43°E., 21.5 ft. mkd: "26 HES 143 CS BT".  
16" D.Fir N.52°E. 15.2 ft. mkd: "26 HES 143 CS BT".  
This corner lies 20 ft. E. of creek, course SE and at foot of mountain.

Maurice E. Farr, USFS - July 1975 - M56-26

-----  
Found - Stump of orig. 26" now 32" fir corner tree, from which bears:  
9" Maple S.43°E., 21.5 ft. scribed: 26 HES 143 CS BT  
16" D.Fir N.52°E. 15.2 ft. scribed: 26 HES 143 CS BT  
Found - Brass cap on 1" pipe (properly) stamped. Brass cap is 2 ft. west of center of corner stump.