

PRIMARY CORNER DESCRIPTION Cor. No. 1, Tract A; HES 179

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12044)

-----  
 It is found necessary to establish a U. S. Location Monument, there being no corners of the public survey within two miles. The most suitable location for the monument is at the point now occupied by the Forest Service Monument, a rock set in a mound of stone, marked and witnessed as described in the field notes of the listing survey, which is on line between corners 1 and 2 of listing survey, as ascertained from a retracement thereof. This location is exceptionally good for the reason that it is in plain view from the trail and because it marks the west boundary of road exemption, it being also corner No. 1 of this survey.

I destroy old Forest Service monument and in its place Set a granite stone 30x9x7", 20" in the ground, for U.S.L.M. No. 179, marked with a cross (X) on top and USLM 179 on south face; from which -

An ash, 26" dia., bears N.52°55'E., 119 lks., marked X USLM 179 BT.

An alder, 14" dia., bears N.18°30'W., 18 lks., marked X USLM 179BT.

Raise a mound of stone, 6 ft. base, 4 ft. high, alongside. The junction of a small creek, locally known as Nicholas Creek, with the South Umpqua River, bears S.45°E., 1.56 chs. West end of a log bridge over Nicholas Creek bears N.82°E., 0.18 chs.

A rocky peak (no name), first peak up river from Ackers Butte, approximately 900 ft. high, bears S.48°30'E., about 1/3 mile distant. Lat. 43°04'N.; Long. 122°40'W.

I begin at cor. No. 1 of this survey, identical with USLM No. 179, which is a granite stone, 9x7x10" above ground, heretofore described, on west side of road exemption.

I mark the stone 1 HES 179 on side facing the claim.

From the corner

An ash, 30" dia., bears N.84°45'E., 40 lks., marked X 1 HES 179 BT.

An alder, 14" dia., bears N.18°30'W., 3.8 lks., marked X 1 HES 179 BT (also scribed for USLM)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

Reported as not found.

Cor. #1 also USLM 179, possible OBTs Fd. - we open, no scribe - no stone.

cont.

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 979010

PRIMARY CORNER DESCRIPTION Cor. No. 1, Tract A; HES 179

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77 & C.S. file 58/162-5A-G

-----

Corner 1 (also USLM 179). There was no trace of the corner stone nor the large mound of stones which was raised alongside the corner by the original surveyor. Two of the original bearing trees were found. The corner location was determined by reference to the original bearing trees, and a monument set and witnessed.

Found - Orig. 14" now 22" Alder BT with rotted blaze bears N.18°30'W., 11.88'

Orig. 30" Ash BT is down, fragmentary scribing visible, stump bears N.84°45'E., 26.4'

Set - 1"x36" galv. pipe with a 2½" brass cap stamped: T29S R1E COR 1 HES 179 ✓ USLM 179 RPLS 1017 1976, from which:

A 12" maple S.65°30'W., 7.9' scribed "COR 1 HES 179 BT"

A 24" ash N.18°30'E., 54.5' scribed "COR 1 HES 179 BT"

Fd. Ok by L. Herzstein, 9/1994 - C.S. File 63/158-1