

PRIMARY CORNER DESCRIPTION Cor. No. 2 Tract A; HES 179

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12045)

Cor. No. 2 (50 ft. above cor. No. 1) identical with cor. No. 2 of listing survey, which I destroy, and in its place Set a granite stone, 25x7x5" 15" in the ground, over a stone marked with a cross for cor. No. 2 of this survey, marked 2 HES 179 on side facing the claim; from which

A cedar, 8" dia., bears N.9°00'W., 24 lks. marked X 2 HES 179 BT.

A granite boulder, 2½x3x3 ft. above ground, bears S.45°00'E., 49 lks., marked X 2 HES 179 BR.

Pits and mound impracticable.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

Reported as not fd. - No cor. stone fd & no OBT as called for - Find "2" bark scribe on 50" fir facing SE & scribe mks on 15" Hemlock facing NE.

Douglas Co. Surveyors Office - Clell Goodwin - Gary Langlitz - Lenora Lading - 12/11/1975 - C.S. File 57/39-30

Found - A stone, 25"x7"x5", firmly set and marked as described in the official record. From Which An OBT, an 8" now 14" red cedar bears N.3°W., 15.8 ft, (rec. N.9°W., 15.8 ft.) alive and nearly healed, now marks visible.

A boulder, 2½x3x3 ft. above ground (measured on down hillside) marked with a chiseled "BR" on top, all other markings gone, bears S 45°E., 32.3 ft.

At the Corner point, we set a 1"x30" I.Pipe with brass cap attached MKD DOUGLAS CO. SURVEYOR T29S R1E
1975 Cor { HES
2 { 179

We place the orig. stone alongside the brass cap. NOTE: This corner is located approx. 300 ft. NW of the South Umpqua Road.

Compass declination setting: 20° East

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77

Found - Brass cap (properly) stamped, from which Orig. 8" now 14" R.Cedar N.3°W. 15.84' w/healed scar Orig. 2½x3x3' boulder mkd: "BR" on top S.45°E. 32.34'