

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 979050

PRIMARY CORNER DESCRIPTION Cor. No. 5 Tract A; HES 179

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12046)

Set a conglomerate stone, 28x7x7", 18" in the ground, over a stone marked with a cross for cor. No. 5 of this survey, marked 5 HES 179 on side facing the claim; from which

A cedar, 16" dia., bears N.18°15'E., 15 lks., mkd. X 5 HES 179 BT.

A yew, 8" dia., bears S.19°30'E., 39 lks., mkd X 5 HES 179 BT.

Raise a mound of earth, 4 ft. base; 2 ft. high, 3½ ft. distant, within the claim.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

Reported as not found.
Nothing Fd - Possibly destroyed by road.

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77 & C.S. File 58/162-5 A-G

No original corner evidence remains of this corner. The proportioned location of the corner falls in the South Umpqua Road. This corner was not monumented.