

PRIMARY CORNER DESCRIPTION Cor. No. 8 Tract B; HES 179

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12047)

-----

Begin at cor. No 8 on easterly side of road exemption on line between cor. No. 1 of Tract A & cor. No. 1 of listing survey. Set a granite stone, 26x10x9", 16" in the ground, over a stone marked with a cross, for cor. No. 8 of this survey, marked 8 HES 179 on side facing the claim; from which

A cedar, 24" dia., bears S.6°30'W., 49 lks., marked X 8 HES 179 BT.

An ash, 30" dia., tears N.10°00'W., 35 lks., marked X 8 HES 179 BT.

Pits and mound impracticable.  
Cor. No. 1 of Tract A bears N.49°01'W., 0.46 chs.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

-----

Reported as not found.  
Possible OBT fd - No scribe, no trace other OBT or cor stone.

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77 & C.S. File 58/162-5 A-G

-----

This corner was destroyed by road construction some time in the past. One original bearing tree remains. This bearing tree is also a bearing tree for Corner 1. The record bearing for this B.T. was found to be in error. The Quadrant of Record is NW, and the tree is in the NE Quadrant. A review of the original survey notes shows that all the adjacent road exemption corners were witnessed by the same bearing trees, as it the case with this bearing tree.

Found - Orig. 30" Ash BT is down, has healed blaze, bears N.10°E., 23.1' (rec. N.10°W. 23.1')

Set - 1"x36" galv. pipe with a 2½" brass cap stamped:  
T29S R1E Cor. 8 ( HES 179 RPLS 1017 1976, from which  
A 40" Cedar S.00°15'W., 44.3' scribed "COR 8 HES 179 BT"  
A 18" Alder S.88°E. 74.6' scribed "COR 8 HES 179 BT"

L.Herzstein for U.S. Forest Service, Sept. 19, 1994 - C.S. File 63/158 F

-----

Found - Sept. 19, 1994: For corner 8 of HES 179, I found a 1" iron post, firmly set, projecting 7" above a 3 ft. dia. mound of stone, with a 2½" brass cap attached and marked as shown on M65-77.  
continued next page

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 979080

PRIMARY CORNER DESCRIPTION Cor. No. 8 Tract B; HES 179

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A roothole, bears N.10°E., 23.1 ft. with a downed alder of indeterminate size lying alongside with a decayed blaze. This tree was also common to corner 1. (orig BT)

42" Red Cedar, bears S.0°15'W., 44.3 ft. with scribe marks "COR 8 HES 179 BT" visible on a partially healed single blaze. This tree was also common to corner 20.

Corner 1 HES # 179 bears N.46°38'36"W., 30.35 ft. which is a 2½" brass cap on a 1" dia. iron post. The brass cap is marked as shown on M65-77.

New BT - 12" W.Fir, bears N.68°45'W., 51.1 ft. scribed "8 HES 179 BT" on a single blaze. A 3/4" dia. brass washer stamped LS 2150 is nailed flush to the BT blaze.

Note - Bearing tree measurements are to the center of the rootcrown and diameters are at breast height. The bearings are true and were rounded to the nearest 15 minutes computed from the control traverse. I determined the magnetic declination to be 20¼° east at this corner.