

PRIMARY CORNER DESCRIPTION Cor. No. 18 Tract B; HES 179

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

HES No. 179 by Frederick W. Rase, surveyor, under special instructions dated Dec. 17, 1915 - Surveyed September 1916 - DCSO records Vol. 28 Page(s) 12051)

Set a granite stone, 24x10x6", 14" in the ground, over a stone mkd. with a cross for cor. No. 18 of this survey, mkd. 18 HES 179 on side facing the claim; from which

 An alder, 8" dia., bears N.81°45'W., 14 lks., marked X 18 HES 179 BT.

 An alder, 8" dia., bears N.63°00'E., 18 lks., marked X 18 HES 179 BT.

Raise a mound of earth, 4 ft. base, 2 ft. high, 3½ ft. within the claim.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - 12/1969 - C.S. File 54/82-90

No trace, on gravel bars - High water probably destroyed this cor

Gordon H. Long, USFS - For: USFS - Aug 1976/Jan 1978 - M65-77 & C.S. File 58/162-5 A-G

All original evidence of this corner has apparently been destroyed by the erosive action of the South Umpqua River. The proportioned corner point is monumented with a brass cap monument and new bearing trees blazed and scribed.

Found - No orig. evidence. At proportionate distance.

Set - 1"x36" gal. pipe with a 2½" brass cap stamped:
 "T29S R1E COR 18 HES 179 RPLS 1017 1976" a memorial stone, marked "X" set under the galv. pipe. - From which bears:
 A 14" Alder N.74°30'E. 118.5' scribed: 18 HES 179 BT
 A 8" maple S.44°E., 63.1' scribed: 18 HES 179 BT

Leonard E. Herzstein, L.S. #2150 - For: U.S.D.A. Forest Service - July 1993 thru Oct. 1994 - C.S. File 63/158-2

At the true corner position, determined by the Grant Boundary method of reestablishing lost corners.

Set - 2½" dia., iron post, 30" long, set 24" in the ground, with a 3' dia., mound of stone raised flush with the top, with a 2½" dia., brass cap attached, stamped;

T29S R1E
H.E.S. 179
COR. 18
. /
L.S. 2150
1994

cont. next pg

TOWNSHIP 29 RANGE 01E POINT IDENTIFIER # 979180

PRIMARY CORNER DESCRIPTION Cor. No. 18 Tract B; HES 179

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

From which the monument set by Long on M 65-77 in 1978:
A 2½" dia., iron post, 30" long, with a 2½" brass cap attached bears S.71°11'40"E., 11.67'. I add the marks "A.M." "L.S.2150" "1994" to the brass cap and reset the monument 6' below the ground.

The bearing trees marked by Long on M 65-77 1978:

18" Alder, bears N.76°30'E., 128.9', with scribe marks "HES 179" visible on a partially healed blaze. This tree is leaning heavily to the West. The bearing and distance are to a 60 penny spike I drove over the center of the rootcrown.

10" Maple, bears S.48°45'E., 72.9', with scribe marks "18" "B" visible on a partially healed double blaze.

And a guard post I set:

A 6' long aluminum post, set 2' in the ground, bears West, 3.0', with Forest Service signs nos. 54-2 and 54-9 attached.

The magnetic declination was found to be 24¾° East.

The Corner is on a rocky flat 14' East above the bank of a secondary channel of the South Umpqua River.