

TOWNSHIP 29 RANGE 01 POINT IDENTIFIER # 133640

PRIMARY CORNER DESCRIPTION W. 1/4 Cor. for Sec. 6 only

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 15 Page(s) 6157)

-----  
Set an Iron post 3 ft. long, 1" dia., 27" in the ground for 1/4 sec. cor. of sec. 6 only, with brass cap mkd.

1/4 S 6  
|  
1922

from which

A Hemlock 8" dia., bears N.77°E., 41 lks. dist. mkd. 1/4 S6 BT.

A Cedar 24" dia., bears S.74°E., 20 lks. dist. mkd. 1/4 S6 BT.

Dennis Gaylord, U.S. Forest Service (Deputized by the DCSO)  
Wit: Randal Lopez - march 16, 1978 - C.S. File 59/46-63

-----  
Found - 2 1/2" brass cap on a 1" I.R. set firmly in the ground with brass cap flush to surface material (duff). This is the W. 1/4 cor. for sec. 6 only, T29-1. I ADD "T29S R1W" to brass cap on East side of stamping 1/4 S6.

A 30" Cedar bears S.74°E., 12.9 ft. (Rec. 13.2 ft.) Has a healed blaze.

An 18" Hemlock bears N.77°E., 27.3 ft. (Rec. 27.06 ft.) Has a healed blaze.

Condition Report Only. Did not Re-monument.  
Placed County BT signs on both trees.