

TOWNSHIP 29 RANGE 01 POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GLO corrective survey by Fred Mensch, Dep. Surveyor, Contract #757 dated Sept. 14, 1904 - (DCSO records Vol. 14 Page 6098)  
-----

Set a porphyry stone 20x15x10", 15" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which  
A R.Fir, 40" dia., bears N.38°E., 14 lks., mkd: 1/4 S18 BT.  
A cedar, 18" dia., bears South, 21 lks., mkd: 1/4 S19 BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - May 21, 1969 - C.S. File 54/82-64  
-----

Found - No trace of 20x15x10 corner stone & both BTs are cut because this corner lies in a logging unit.  
40" R.Fir now 48" windfall stump, N.38°E., 9.2 ft. shows a face.  
18" Cedar, now 28" stump, South 13.9 ft. Opened & fd. scribe of a "B"

Set brass cap at 1/4 corner from bearing & dist. from both BTs  
mkd: COUNTY SURVEYORS T29S R1W  
OFFICE 1/4 S 18  
1969 S 19

New BTs- 6" Hemlock S.64°E., 204.4 ft. scribed 1/4 S19 CS BT  
22" Cedar S.34°E., 223.9 ft. scribed 1/4 S19 CS BT

Note - 5' metal fence post by BC.  
Bearing objects out range in north. Plus this corner lies in a logged over unit 25' west of creek.